

SAFETY RECALL N946 – REAR CAMERA WATER INGRESS

SAFETY RECALL N946– REAR CAMERA WATER INGRESS	
AFFECTED MODELS	22-23MY Range Rover (L460)
VOLUME AFFECTED	11,961 US 616 CAN
REPAIR	A concern has been identified where, on certain Range Rover vehicles, water could get into the rear-facing tailgate mounted camera. This water ingress can cause a distorted image, or no image at all, to be displayed on the touchscreen. A new rear camera and calibration is required.
REPAIR TIME	0.9 hr + DIDO
CAMPAIGN LAUNCH	March 25th , 2025
NOTES	Retailers should repair affected vehicles at the next earliest opportunity. Affected VIN are flagged in the warranty portal and TOPIx. BBSS shows affected used vehicles.. Parts Bulletin 242503.047 has been published for the US market, please carefully review; for details of the special parts ordering processes being used with this recall.