



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

February 5, 2025

Mr. Jim Johnson
Manager, Vehicle Safety & Regulatory Compliance
New Flyer of America, Inc.
711 Kernaghan Avenue
Winnipeg, MB R2C3T4

NEF-107HG
25V-053

Subject: Fuel Filter Hoses May Disconnect and Leak Fuel

Dear Mr. Johnson:

This letter serves to acknowledge New Flyer of America, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

NEW FLYER/XD35/2024
NEW FLYER/XD40/2024
NEW FLYER/XD60/2024
NEW FLYER/XDE60/2023-2024

Mfr's Report Date: February 3, 2025

NHTSA Campaign Number: 25V-053

Components:

FUEL SYSTEM, DIESEL:DELIVERY:HOSES, LINES/PIPING, AND FITTINGS

Potential Number of Units Affected: 210

Problem Description:

New Flyer of America, Inc. (New Flyer) is recalling certain 2023-2024 XDE60, 2024 XD35, XD40, and XD60 transit buses equipped with Cummins L9 diesel engines. The remote fuel filter hoses may separate from the fitting, causing a fuel leak and an engine stall.

Consequence:

A fuel leak in the presence of an ignition source increases the risk of a fire. An engine stall increases the risk of a crash.

Remedy:

Cummins will replace the fuel hoses, free of charge. Owner notification letters are expected to be mailed March 11, 2025. Owners may contact Cummins customer service at 1-800-286-6467 or New Flyer customer service at 1-800-241-2947.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153) or go to [nhtsa.gov](https://www.nhtsa.gov).

Please be reminded of the following requirements:



You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in 49 U.S.C. § 30118(f), submission of eight consecutive quarterly reports followed by three annual reports is required. As described in 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter. The first of three consecutive annual status reports will be due on, or before, 1 year after the eighth quarterly report was submitted.

New Flyer of America, Inc.'s contact for this recall will be Hensly Guerra who may be reached by email at hensly.guerra1@dot.gov. We look forward to working with you.

Sincerely,



Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement