

Part 573 Safety Recall Report

25V-189

Manufacturer Name : Temsa**Submission Date :** APR 17, 2025**NHTSA Recall No. :** 25V-189**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Temsa

Address : Temsa North America

404 Zell Drive Orlando FL 32824

Company phone : 8336283672

Population :

Number of potentially involved : 11

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2024-2025 TEMSA TS45

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : DIESEL

Descriptive Information : This recall covers only 11 units of the 2024 & 2025 model year TS45 buses.

Production Dates : APR 29, 2024 - JUL 11, 2024

VIN Range 1 : Begin : NLTEJXA96R1000534 End : NLTEJXB95S1000562 Not sequential**Description of Noncompliance :**

Description of the Noncompliance : The Gross Vehicle Weight Rating (GVWR) listed on the certification labels are incorrect, which can allow the vehicle to be overloaded. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 120, "Wheels and Rims - Other than Passenger Cars."

FMVSS 1 : 120 - Wheels and rims- other than passenger cars

FMVSS 2 : NR

Description of the Safety Risk : A small number of vehicles have been manufactured with the incorrect value shown on the Certification Label's Gross Vehicle Weight Rating (GVWR). Because an incorrect value is given for the GVWR, customers may unknowingly exceed the GVWR. Exceeding the GVWR of the vehicle can lead to loss of vehicle stability and increase risk of a crash.

Description of the Cause : A typographical error occurred while entering the GVWR into the system

Identification of Any Warning that can Occur : NR

Involved Components :

Component Name 1 : Certification Plate

Component Description : Certification Plate

Component Part Number : 9050-857Y

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

During an internal audit in March 2025, it is discovered that an incorrect GVWR had been entered in the database which is used to write the certification label. TEMSA investigated and determined the affected vehicles. And on March 21st, 2025, TEMSA decided to conduct a voluntary safety recall.

Description of Remedy :

Description of Remedy Program : The old VIN Plate will be replaced with the corrected one.

How Remedy Component Differs from Recalled Component : The corrected certification label of TS45 vehicle will have GVWR as 51500 lbs. The old certification label has GVWR as "54000 lbs."

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Temsa will send notifications to customers after receiving approval by NHTSA for Temsa's draft customer notification letter. Note: No dealers involved in recall

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : APR 10, 2025 - MAY 08, 2025

* NR - Not Reported