#### OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

# 25V-292

**Manufacturer Name:** K.Z., Inc.

**Submission Date:** MAY 06, 2025

NHTSA Recall No.: 25V-292

**Manufacturer Recall No.:** NR



#### **Manufacturer Information:**

Manufacturer Name: K.Z., Inc.

Address: 0985 N 900W

Shipshewana IN 46565

Company phone: 800-768-4016x154/153

# **Population:**

Number of potentially involved: 45 Estimated percentage with defect: 100 %

#### **Vehicle Information:**

Vehicle 1: 2025-2025 KZ RV Durango Gold

Vehicle Type: TRAILERS

Body Style : Power Train : NR

Descriptive Information: KZ RV was notified by MORryde about the their recall 25E026. The population was

then identified using MORryde's provided part numbers and affected dates.

Production Dates: JUL 10, 2024 - APR 09, 2025

VIN Range 1 : Begin : NR End : NR Not sequential

#### **Description of Defect:**

Description of the Defect: MORryde Recall 25E-026 - there is a bracket that is used on the side of an RV

that has a receiver for a removable step assembly to clip into. This receiver is installed using a thread locking fluid to retain this assembly. MORryde found that there are parts that did not have this thread locking component installed

during assembly.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: If this receiver becomes loose while being used, it can disengage from the

fastener that is used to assemble it to the bracket and disconnect from the bracket allowing the step assembly to fall from its use location. This has the potential to cause personal injury if the step is being used when this happens.

Description of the Cause: The receiving bracket for the step was not built properly with the locking

component.

Identification of Any Warning A loose step receiver bracket.

that can Occur:

# **Involved Components:**

Component Name 1: Clip-on bracket; step bracket Component Description: Clip-on bracket; step bracket

Component Part Number: THP56-143; THP-D106-W1, THP-DW137-W1

## **Supplier Identification:**

# **Component Manufacturer**

Name: MORryde

Address: 1966 Sterling Avenue

Elkhart Indiana 46516

**Country: United States** 

# **Chronology:**

On April 25, 2025, a MORryde sales representative informed KZ of the recall. All affected units in the yard were placed on hold. On April 26th, units in the yard were repaired. On April 27, KZ received official notification via email from MORryde regarding the recall. KZ's safety committee met on May 1st and agreed to issue a recall. No warranty, consumer complaints, or injury claims have been received.

#### **Description of Remedy:**

Description of Remedy Program: The remedy is to replace the step bracket with a properly built bracket. All

repairs will be completed at no cost to the owner. Reimbursement will

follow the general reimbursement plan that is on file with NHTSA.

How Remedy Component Differs The remedied RVs will have a bracket that was built with the thread

from Recalled Component: locking compound that will prevent the bracket from coming loose.

Identify How/When Recall Condition The recall condition will be corrected because the new parts will be was Corrected in Production: properly built by MORryde. The properly built brackets will be used in

place of defective ones that KZ's received in the past.

### **Recall Schedule:**

Description of Recall Schedule: KZ RV has the utmost urgency in notifying owners about a recall that

affects their vehicle. Letters will be sent once all pertinent information

has been gathered.

# **Part 573 Safety Recall Report**

25V-292

Page 3

Planned Dealer Notification Date : JUL 05, 2025 - JUL 05, 2025 Planned Owner Notification Date : JUL 05, 2025 - JUL 05, 2025

\* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573