



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

25V653

Manufacturer Name: Thor Motor Coach

Submission Date: Sep 30, 2025

NHTSA Recall No.: 25V653

Manufacturer Recall No.: RC000331

Manufacturer Information

Population

Manufacturer Name: Thor Motor Coach

Address: PO Box 1486
701 County Road 15
Elkhart IN, 46515

Total number of potentially involved: 23

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2024-2025 THOR MOTOR COACH LUMINATE

Product Category: Buses, Medium & Heavy Vehicles

Product Type: Recreational Vehicle

Fuel / Propulsion: Compressed Natural Gas

Production Dates: Jul 20, 2023 - Jun 25, 2024

Number of potentially involved: 15

Descriptive Information:

Welded LP mounting tubes located in front of rear axle

Vehicle 2: 2024-2025 THOR MOTOR COACH INDIGO

Product Category: Buses, Medium & Heavy Vehicles

Product Type: Recreational Vehicle

Fuel / Propulsion: Compressed Natural Gas

Production Dates: Dec 13, 2023 - Jul 24, 2024

Number of potentially involved: 8

Descriptive Information:

Welded LP mounting tubes located in front of rear axle

Defect / Noncompliance Description

Part 573 Safety Recall Report**25V653****Description of the defect or noncompliance:**

The LP tank support tube is too short and has an inferior chassis weld.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

If the LP tank support tube weld separates from the chassis the LP tank can drop leading to an increased risk of a crash, injury or fire.

Description of the cause:

Identification of any warning that can occur:

Component Manufacturer

Tier of Supplier:

Supplier Type:

Name:

Address:

Country:

Involved Components

Component Name 1:

Component Description:

Component Part Number:

Chronology

11/15/2024 - Warranty request submitted for LP tank separation by selling dealer (Canada) while the owner is traveling in the U.S. (Texas). The purpose was to report the incident and note a sublet repair will follow.

3/4/2025 - Selling dealer (Canada) submitted a claim for the proper LP tank repair after the owner returned to Canada.

Part 573 Safety Recall Report

25V653

3/11/2025 - TMC Engineering was made aware of the LP tank bracket separation at a Canadian dealer due to inadequate welds on the support tubing. Repair instructions were generated for servicing dealer to follow. TMC Engineering opened and investigation on LP tank installation.

5/12/2025 - TMC Engineering continued to evaluate the issue. All parties monitoring for additional claims.

9/12/2025 - The original issue was found posted on social media.

9/29/2025 - TMC Safety Committee met and voted to issue a voluntary recall.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type:

Consumer Advisories: Do Not Drive Park Outside

Description of remedy program:

How remedy component differs from recalled component:

Identify how/when recall condition was corrected in production:

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule

Description of recall schedule:

Thor Motor Coach has the utmost urgency in notifying owners about a recall that affects their vehicle. Letters will be sent out once all pertinent information has been gathered.

Part 573 Safety Recall Report**25V653**

Planned Dealer Notification Date: Nov 24, 2025 - Nov 24, 2025 No Dealers

Planned Interim Owner Notification Date: Nov 24, 2025 - Nov 24, 2025 No Owners

Planned Remedy Owner Notification Date: Nov 24, 2025 - Nov 24, 2025 Phased Recall

Date when VIN will be searchable: