



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

25V754

Manufacturer Name: McNeilus Truck & Manufacturing, Inc.

Submission Date: Nov 03, 2025

NHTSA Recall No.: 25V754

Manufacturer Recall No.:

Manufacturer Information

Population

Manufacturer Name: McNeilus Truck & Manufacturing, Inc.
Address: 524 County Road 34 East
P.O. Box 70
Dodge Center MN, 55927

Total number of potentially involved: 115
Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2024-2025 McNeilus Volterra

Product Category:

Product Type:

Fuel / Propulsion: Electric Battery Power

Production Dates: Aug 30, 2024 - Aug 31, 2025

Number of potentially involved: 115

Descriptive Information:

McNeilus Volterra ZSL products were identified a missing intermediate side reflex reflectors required by 49 CFR 571.108.

Defect / Noncompliance Description

Description of the defect or noncompliance:

The affected vehicles are trucks (refuse vehicles) 30 feet or longer and are not equipped with intermediate side reflex reflectors as required by FMVSS 108.

FMVSS1: 108 - Lamps, reflective devices, and assoc. Equipment

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

Without the required intermediate side reflex reflectors, the overall length of the vehicle may be less conspicuous to other drivers, potentially increasing the risk of a crash.

Part 573 Safety Recall Report

25V754**Description of the cause:**

During manufacturing of the refuse body, the intermediate amber reflex reflectors were not installed.

Identification of any warning that can occur:

None.

Component Manufacturer

Tier of Supplier:**Supplier Type:****Name:****Address:****Country:**

Involved Components

Component Name 1: Intermediate Reflex Reflector**Component Description:** Intermediate Reflex Reflector**Component Part Number:** 1530338

Chronology

In September 2025, in the course of considering a separate and unrelated issue, it came to McNeilus' attention that a Volterra model vehicle was not equipped with amber reflex reflectors at the middle of the refuse body. McNeilus initiated an analysis of the issue including whether the individual vehicle was representative of broader vehicle production and whether the reflectors are required equipment under FMVSS 108. McNeilus' investigation determined that the manufacturer of the vehicle body had omitted the intermediate reflex reflectors during production and the reflectors are a required item of equipment for vehicles 30 feet or more in length. On October 29, 2025, McNeilus determined the vehicles do not comply with the requirements of FMVSS 108 and would conduct a safety recall to address the affected units in the field.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Repair

Part 573 Safety Recall Report**25V754**

Consumer Advisories: Do Not Drive Park Outside

Description of remedy program:

McNeilus will have technicians install the intermediate reflex reflectors at no cost to the customers.

How remedy component differs from recalled component:

Amber reflectors will be installed on the middle sides of the body.

Identify how/when recall condition was corrected in production:

A stop ship was implemented and all units in McNeilus' s possession were corrected.

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule**Description of recall schedule:**

Notifications to customers will be made via a customer letter. The 577 customer letter will be mailed pending NHTSA approval.

Planned Dealer Notification Date: Dec 22, 2025 - Dec 22, 2025 No Dealers

Planned Interim Owner Notification Date: No Owners

Planned Remedy Owner Notification Date: Dec 22, 2025 - Dec 22, 2025 Phased Recall

Date when VIN will be searchable: