



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

25V791

Manufacturer Name: Thor Motor Coach

Submission Date: Dec 17, 2025

NHTSA Recall No.: 25V791

Manufacturer Recall No.: RC000336

Manufacturer Information

Population

Manufacturer Name: Thor Motor Coach

Address: PO Box 1486
701 County Road 15
Elkhart IN, 46515

Total number of potentially involved: 4,763

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2023-2024 THOR MOTOR COACH DAZZLE

Product Category: Light Vehicles

Product Type:

Fuel / Propulsion:

Production Dates: Sep 07, 2022 - Mar 28, 2024

Number of potentially involved: 356

Descriptive Information:

TMC claim history discovered the potential for loose or broken solar panel mount brackets.

Vehicle 2: 2023-2023 THOR MOTOR COACH TRANQUILITY

Product Category: Light Vehicles

Product Type:

Fuel / Propulsion:

Production Dates: Mar 24, 2022 - Mar 09, 2023

Number of potentially involved: 546

Descriptive Information:

TMC claim history discovered the potential for loose or broken solar panel mount brackets.

Vehicle 3: 2024-2024 THOR MOTOR COACH FREEDOM ELITE VAN

Product Category: Light Vehicles

Part 573 Safety Recall Report**25V791****Product Type:****Fuel / Propulsion:****Production Dates:** May 30, 2023 - Aug 09, 2023**Number of potentially involved:** 147**Descriptive Information:**

TMC claim history discovered the potential for loose or broken solar panel mount brackets.

Vehicle 4: 2023-2023 THOR MOTOR COACH SANCTUARY**Product Category:** Light Vehicles**Product Type:****Fuel / Propulsion:****Production Dates:** Mar 24, 2022 - Mar 13, 2023**Number of potentially involved:** 646**Descriptive Information:**

TMC claim history discovered the potential for loose or broken solar panel mount brackets.

Vehicle 5: 2023-2024 THOR MOTOR COACH TWIST**Product Category:** Light Vehicles**Product Type:****Fuel / Propulsion:****Production Dates:** Dec 05, 2022 - Mar 11, 2024**Number of potentially involved:** 196**Descriptive Information:**

TMC claim history discovered the potential for loose or broken solar panel mount brackets.

Vehicle 6: 2022-2024 THOR MOTOR COACH SEQUENCE**Product Category:** Buses, Medium & Heavy Vehicles**Product Type:****Fuel / Propulsion:****Production Dates:** Mar 24, 2021 - Mar 28, 2024**Number of potentially involved:** 2,073**Descriptive Information:**

Part 573 Safety Recall Report

25V791

TMC claim history discovered the potential for loose or broken solar panel mount brackets.

Vehicle 7: 2022-2024 THOR MOTOR COACH TELLARO

Product Category: Buses, Medium & Heavy Vehicles

Product Type:

Fuel / Propulsion:

Production Dates: Mar 24, 2021 - Mar 28, 2024

Number of potentially involved: 799

Descriptive Information:

TMC claim history discovered the potential for loose or broken solar panel mount brackets.

Defect / Noncompliance Description

Description of the defect or noncompliance:

The solar panel mount brackets may become loose or break allowing the solar panel to detach from the roof.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

If the solar panel detaches from the roof that will increase the risk of a crash and/or personal injury.

Description of the cause:

Production failed to installed washers to the mounting brackets as designed.

Identification of any warning that can occur:

Loose or damaged solar panel bracket.

Component Manufacturer

Tier of Supplier:

Supplier Type:

Name:

Part 573 Safety Recall Report

25V791**Address:****Country:**

Involved Components

Component Name 1: Solar Panel bracket**Component Description:** Bracket, Solar Panel**Component Part Number:** 0443684

Chronology

9/23/2025 -NHTSA questions TMC about 2 solar panel VOQs.

9/24/2025 - 10/27/2025 -Email dialog between TMC and NHTSA ongoing.

10/27/2025 -TMC expanded data review.

11/5/2025 -Thor Industries informs NHTSA that a safety committee meeting is being scheduled.

11/7/2025 -A safety committee meeting is held to review this issue. Further review of the data is requested by TMC.

11/11/2025 -A safety committee meeting is held to finalize scope of the issue. A recall is deemed necessary. TMC has 75 warranty claims reported with no deaths or injuries.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Replace**Consumer Advisories:** Do Not Drive Park Outside**Description of remedy program:**

Instructions state to inspect for missing washers of the solar panel mounting hardware. The repair will be done at no cost to the owner. Reimbursement will follow the general reimbursement policy on file with NHTSA.

How remedy component differs from recalled component:

The missing washer strengthens the durability of the solar panel securement.

Identify how/when recall condition was corrected in production:

Part 573 Safety Recall Report

25V791

11/7/2025 -Meeting with production managers were instructed to follow engineering work instructions pertaining to solar panel installation.

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule

Description of recall schedule:

- Planned Dealer Notification Date:** Jan 12, 2026 - Jan 12, 2026 No Dealers
- Planned Interim Owner Notification Date:** Jan 05, 2026 - Jan 05, 2026 No Owners
- Planned Remedy Owner Notification Date:** Jan 12, 2026 - Jan 12, 2026 Phased Recall

Date when VIN will be searchable: