



U.S. Department  
of Transportation

National Highway  
Traffic Safety  
Administration

## Part 573 Safety Recall Report

# 25V792

**Manufacturer Name:** Thor Motor Coach

**Submission Date:** Jan 20, 2026

**NHTSA Recall No.:** 25V792

**Manufacturer Recall No.:** RC000337

### Manufacturer Information

### Population

**Manufacturer Name:** Thor Motor Coach

**Address:** PO Box 1486  
701 County Road 15  
Elkhart IN, 46515

**Total number of potentially involved:** 2,345

**Estimated percentage with defect:** 100%

### Vehicle Information

**Vehicle 1:** 2023-2024 THOR MOTOR COACH RIZE

**Product Category:** Light Vehicles

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Mar 25, 2022 - Mar 05, 2024

**Number of potentially involved:** 288

**Descriptive Information:**

TMC claim history discovered the potential for loose solar panels from insufficient adhesive.

**Vehicle 2:** 2023-2024 THOR MOTOR COACH SCOPE

**Product Category:** Light Vehicles

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Mar 25, 2022 - Feb 27, 2024

**Number of potentially involved:** 283

**Descriptive Information:**

TMC claim history discovered the potential for loose solar panels from insufficient adhesive.

**Vehicle 3:** 2022-2024 THOR MOTOR COACH TELLARO

**Product Category:** Buses, Medium & Heavy Vehicles

**Part 573 Safety Recall Report****25V792****Product Type:****Fuel / Propulsion:****Production Dates:** Mar 24, 2021 - Mar 26, 2024**Number of potentially involved:** 1,176**Descriptive Information:**

TMC claim history discovered the potential for loose solar panels from insufficient adhesive.

**Vehicle 4:** 2023-2024 THOR MOTOR COACH SEQUENCE**Product Category:** Light Vehicles**Product Type:****Fuel / Propulsion:****Production Dates:** Mar 24, 2022 - Mar 26, 2024**Number of potentially involved:** 416**Descriptive Information:**

TMC claim history discovered the potential for loose solar panels from insufficient adhesive.

**Vehicle 5:** 2023-2024 THOR MOTOR COACH DAZZLE**Product Category:** Light Vehicles**Product Type:****Fuel / Propulsion:****Production Dates:** Nov 09, 2022 - Mar 14, 2024**Number of potentially involved:** 147**Descriptive Information:**

TMC claim history discovered the potential for loose solar panels from insufficient adhesive.

**Vehicle 6:** 2024-2024 THOR MOTOR COACH TWIST**Product Category:** Light Vehicles**Product Type:****Fuel / Propulsion:****Production Dates:** Apr 17, 2023 - Mar 04, 2024**Number of potentially involved:** 35**Descriptive Information:**

# Part 573 Safety Recall Report

# 25V792

TMC claim history discovered the potential for loose solar panels from insufficient adhesive.

## Defect / Noncompliance Description

### Description of the defect or noncompliance:

The solar panel adhesive may not be sufficient allowing the solar panel to detach from the roof.

**FMVSS1:**

**FMVSS2:**

### Description of the safety risk, including crash, fire, death, injury:

If the solar panel detaches from the roof that will increase the risk of a crash and/or personal injury.

### Description of the cause:

Insufficient sealant used to adhere solar panel to the roof of the RV.

### Identification of any warning that can occur:

Loose solar panel adhesion.

## Component Manufacturer

**Tier of Supplier:**

**Supplier Type:**

**Name:**

**Address:**

**Country:**

## Involved Components

**Component Name 1:** Sealant

**Component Description:** Sealant

**Component Part Number:** 0134891

## Chronology

**Part 573 Safety Recall Report****25V792**

9/23/2025 -NHTSA questions TMC about 2 solar panel VOQs.

9/24/2025 - 10/27/2025 -Email dialog between TMC and NHTSA ongoing.

10/27/2025 -TMC expanded data review.

11/5/2025 -Thor Industries informs NHTSA that a safety committee meeting is being scheduled.

11/7/2025 -A safety committee meeting is held to review this issue. Further review of the data is requested by TMC.

11/11/2025 -A safety committee meeting is held to finalize scope of the issue. A recall is deemed necessary. TMC has 21 warranty claims reported with no deaths or injuries.

**Related NHTSA Recall Number:**

**Description of Remedy**

**Remedy Type:**

**Consumer Advisories:**  Do Not Drive  Park Outside

**Description of remedy program:**

**How remedy component differs from recalled component:**

**Identify how/when recall condition was corrected in production:**

**Reimbursement Plan**

Manufacturer used general reimbursement plan on file.

**Recall Schedule**

**Description of recall schedule:**

**Planned Dealer Notification Date:** Jan 12, 2026 - Jan 12, 2026

No Dealers

# Part 573 Safety Recall Report

25V792

**Planned Interim Owner Notification Date:** Jan 05, 2026 - Jan 05, 2026  No Owners

**Planned Remedy Owner Notification Date:** Jan 12, 2026 - Jan 12, 2026  Phased Recall

**Date when VIN will be searchable:**