



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

25V792

Manufacturer Name: Thor Motor Coach

Submission Date: Feb 04, 2026

NHTSA Recall No.: 25V792

Manufacturer Recall No.: RC000337

Manufacturer Information

Population

Manufacturer Name: Thor Motor Coach

Address: PO Box 1486
701 County Road 15
Elkhart IN, 46515

Total number of potentially involved: 1,792

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2023-2024 THOR MOTOR COACH DAZZLE

Product Category: Light Vehicles

Product Type:

Fuel / Propulsion:

Production Dates: Nov 09, 2022 - Mar 14, 2024

Number of potentially involved: 140

Descriptive Information:

TMC claim history discovered the potential for loose solar panels from insufficient adhesive.

Vehicle 2: 2023-2024 THOR MOTOR COACH SEQUENCE

Product Category: Light Vehicles

Product Type:

Fuel / Propulsion:

Production Dates: Mar 24, 2022 - Mar 26, 2024

Number of potentially involved: 396

Descriptive Information:

TMC claim history discovered the potential for loose solar panels from insufficient adhesive.

Vehicle 3: 2024-2024 THOR MOTOR COACH TWIST

Product Category: Light Vehicles

Part 573 Safety Recall Report

25V792**Product Type:****Fuel / Propulsion:****Production Dates:** Apr 17, 2023 - Mar 04, 2024**Number of potentially involved:** 34**Descriptive Information:**

TMC claim history discovered the potential for loose solar panels from insufficient adhesive.

Vehicle 4: 2022-2024 THOR MOTOR COACH TELLARO**Product Category:** Buses, Medium & Heavy Vehicles**Product Type:****Fuel / Propulsion:****Production Dates:** Mar 24, 2021 - Mar 26, 2024**Number of potentially involved:** 719**Descriptive Information:**

TMC claim history discovered the potential for loose solar panels from insufficient adhesive.

Vehicle 5: 2023-2024 THOR MOTOR COACH RIZE**Product Category:** Light Vehicles**Product Type:****Fuel / Propulsion:****Production Dates:** Mar 25, 2022 - Mar 05, 2024**Number of potentially involved:** 238**Descriptive Information:**

TMC claim history discovered the potential for loose solar panels from insufficient adhesive.

Vehicle 6: 2023-2024 THOR MOTOR COACH SCOPE**Product Category:** Light Vehicles**Product Type:****Fuel / Propulsion:****Production Dates:** Mar 25, 2022 - Feb 27, 2024**Number of potentially involved:** 265**Descriptive Information:**

Part 573 Safety Recall Report

25V792

TMC claim history discovered the potential for loose solar panels from insufficient adhesive.

Defect / Noncompliance Description

Description of the defect or noncompliance:

The solar panel adhesive may not be sufficient allowing the solar panel to detach from the roof.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

If the solar panel detaches from the roof that will increase the risk of a crash and/or personal injury.

Description of the cause:

Insufficient sealant used to adhere solar panel to the roof of the RV.

Identification of any warning that can occur:

Loose solar panel adhesion.

Component Manufacturer

Tier of Supplier:

Supplier Type:

Name:

Address:

Country:

Involved Components

Component Name 1: Sealant

Component Description: Sealant

Component Part Number: 0134891

Chronology

Part 573 Safety Recall Report

25V792

9/23/2025 -NHTSA questions TMC about 2 solar panel VOQs.

9/24/2025 - 10/27/2025 -Email dialog between TMC and NHTSA ongoing.

10/27/2025 -TMC expanded data review.

11/5/2025 -Thor Industries informs NHTSA that a safety committee meeting is being scheduled.

11/7/2025 -A safety committee meeting is held to review this issue. Further review of the data is requested by TMC.

11/11/2025 -A safety committee meeting is held to finalize scope of the issue. A recall is deemed necessary. TMC has 21 warranty claims reported with no deaths or injuries.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Replace

Consumer Advisories: ☐ Do Not Drive ☐ Park Outside

Description of remedy program:

Instructions state to remove the solar panel sealant and replace with a different exterior sealant. The repair will be done at no cost to the owner. Reimbursement will follow the general reimbursement policy on file with NHTSA.

How remedy component differs from recalled component:

The replacement sealant has a stronger bond to the solar panel and RV roof.

Identify how/when recall condition was corrected in production:

1/15/2026 -Engineering created new instructions directing production how to seal the solar panel to roof and specified the new sealant.

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule

Description of recall schedule:

Part 573 Safety Recall Report**25V792****Planned Dealer Notification Date:** Mar 12, 2026 - Mar 12, 2026☐ No Dealers**Planned Interim Owner Notification Date:** Jan 12, 2026 - Jan 12, 2026☐ No Owners**Planned Remedy Owner Notification Date:** Mar 12, 2026 - Mar 12, 2026☐ Phased Recall**Date when VIN will be searchable:**