

ASA0 Recall campaign - Check rear seat belt buckles and rework if necessary

ASA0 Recall campaign - Check rear seat belt buckles and rework if necessary

ID Number	ASA0
Affected Model(s)	911 (992)
Affected Model Year(s)	2023
VIN List	Attached below
Number of Affected Vehicles	277
Issue Description	On the affected vehicles, there is a possibility that the rear seat belt buckles were not bolted to design specifications and could potentially loosen over time.
What should Porsche Centers do?	Please arrange for the remedy to be carried out on affected vehicles as soon as possible. As of the time of this posting (2/28/25) the remedy is immediately available.
What will Porsche do?	Vehicles will have the remedy performed once it is available. As of the time of this posting (2/28/25) the remedy is immediately available.
Technical Information	ASA0
Parts Status	Status 1 - Parts can be ordered via PPL as needed.
Customer Letter	To be posted at a later date.
Customer Reactive Statement	Our first priority is the safety and quality of our cars. We have identified a potential issue with rear seatbelt buckle bolts in certain specific 911 vehicles that were manufactured during a defined production range. There are no reports of incidents connected to this issue. We will notify customers via letter, and vehicles will be repaired free of charge.

ASA0 Recall campaign - Check rear seat belt buckles and rework if necessary

Attachments

1. [VIN_List_Report_ASA0_2025-02-28_V2.xlsx](#)