

External Email Think Before You Click.



Date: February 26, 2025

ATTN: All Dealership Personnel

Subject: Important Safety Recall Information I-25-01 Released

IMPORTANT SAFETY NOTICE
Stop Sale

IMPORTANT STOP SALE NOTICE!
Stop selling affected vehicles immediately.

Safety Recall I-25-01

Indian Motorcycle has determined that some Model Year 2025 Challenger, Pursuit, Roadmaster Elite, and Springfield motorcycles may have been built with a fuel pump with an incorrectly crimped wire by the supplier. This may result in a fuel pump failure and vehicle stall during operation, which increases the risk of a crash and serious injury. This affects less than 50 motorcycles.

To address this concern, Indian Motorcycle has released this Safety Recall with instructions to replace the fuel pump on affected motorcycles.

[View I-25-01 Safety Recall](#)

What Dealers Should Do?

As of February 26, 2025, **YOU MUST NOT SELL OR DELIVER** any affected **NEW OR USED Model Year 2025** Challenger, Pursuit, Roadmaster Elite, and Springfield motorcycles until it is repaired according to the Safety Recall bulletin.

Dealers are required to review their sales records and make arrangements with customers for Recall completion. In addition to consumer units, dealers are required to correct any affected units in their inventory.

Affected Units

2025:

- Challenger
- Pursuit
- Roadmaster Elite
- Springfield

Reference Unit Inquiry on the dealer website or the Service Communications list on the STOP site to look up affected units.

Please contact Indian Motorcycle Service by phone at 800-330-9407 or through Ask Polaris with any questions or concerns.

Thank you for your cooperation in this matter.

Sincerely,

- Indian Motorcycle Service