



REV Recreation Group
P.O. Box 1007
Decatur, IN 46733
(800) 816-9825

**IMPORTANT RECALL INFORMATION #250221REV
APRIL2025
NHTSA #25V121 TC #2025-107**

**TO: ALL REV RECREATION GROUP DEALER PRINCIPALS,
SERVICE MANAGERS AND PARTS MANAGERS**

SUBJECT: RECALL CAMPAIGN #250221REV - EXHAUST TIPS

REV Recreation Group, Inc., on behalf of its manufacturing center located in Decatur, Indiana, is requesting your assistance in conducting a voluntary recall notification campaign in accordance with the United States National Traffic and Motor Vehicle Safety Act and the Motor Vehicle Safety Act.

REV Recreation Group, Inc. has decided that a safety defect relating to motor vehicle safety exists on **certain** Fleetwood and Holiday Rambler, brand Class A gasoline motorhomes:

Fleetwood Products

Model Year(s) 2022-2025 Bounder
Model Year(s) 2022-2025 Flair
Model Year(s) 2023-2025 Flex
Model Year(s) 2022-2025 Fortis
Model Year(s) 2022-2023 Southwind

Manufactured date range

June 04, 2021 – February 11, 2025
May 28, 2021 – February 11, 2025
April 18, 2022 – February 11, 2025
May 28, 2021 – February 11, 2025
June 23, 2021 – April 13, 2023

Holiday Rambler Products

Model Year(s) 2022-2025 Admiral
Model Year(s) 2023-2025 Eclipse
Model Year(s) 2019-2025 Invicta
Model Year(s) 2023-2025 Vacationer

Manufactured date range

May 28, 2021 – February 11, 2025
March. 23, 2021 – February 11, 2025
May 28, 2021 – February 11, 2025
June 10, 2021 – February 11, 2025

Models: ALL

We are notifying the owners of the affected vehicles in order to correct the problem outline below. Copies of the U.S. and Canadian owner notification letters and Service Bulletin are attached for your information.

WHAT IS THE PROBLEM?

On motorhomes affected by this recall campaign the main engine exhaust tip can become detached in certain circumstances due to a REV RV weld failure on Ford chassis class A motor homes.

WHAT SHOULD YOU DO?

Stock units must not be sold until the recall has been completed. Owners of the above-mentioned motorhomes have been told that the carbon monoxide detector may alarm and/or the compartment liner melt causing a detectable odor. In addition, a detached exhaust tip can become a road hazard for other road users, increasing the risk of a crash. In the event that you are contacted by a customer, please verify eligibility by referring to the serial number range listed in the attached **Recall Service Bulletin #250221REV** prior to beginning repairs. Contact REV RV Technical Support at (800) 816-9825 for repair authorization, and REV RV Parts at (800) 509-3417 to order replacement parts.

Once repairs have been completed according to **Recall Service Bulletin #250221REV**, have the customer sign your dealership's **Internal Repair Order**. Warranty labor claims are to be submitted electronically to REV Recreation Group. **Customers will not be charged for these repairs.**

*If you have one of these vehicles in your inventory, you will be mailed a Safety Recall Notice for that specific motorhome. **REV Recreation Group dealers are required to make repairs to stock units on dealer lots prior to sale or lease.***



Federal Law (Section 154 of the National Highway Traffic and Motor Vehicle Safety Act) of 1966 requires that: If you have received a notice of recall or failure to comply from REV Recreation Group, Inc. or any component manufacturer, you must repair or otherwise correct the defect on vehicles remaining in your inventory according to the notification before selling or leasing the vehicles. Any vehicle lessor receiving this recall notice must forward a copy of the notice to the lessee within ten days.

Please carefully review this entire package with your parts and service staff to familiarize them with the step-by-step procedure and implement the Voluntary Recall Campaign.

Thank you for helping REV Recreation Group with its continuing efforts to maintain customer satisfaction. If you have any questions, please contact your REV Recreation Group Service Center.

Sincerely,

REV RECREATION GROUP, INC.

Attachments: Recall 250221REV US Owners Letters
Recall #250221REV Canadian Owners Letters
Recall #250221REV Service Bulletin