

SAFETY RECALL ACTION NOTICE 630: SPEED TWIN 1200/RS & SPEED TWIN 900

SAFETY RECALL ACTION NOTICE 630

REAR INDICATORS REPLACEMENT

<u>MODEL CODE</u>	<u>MODEL</u>	<u>MODEL YEAR</u>
DD5	Speed Twin 1200	2025
DH5	Speed Twin 1200 RS	2025
DP5	Speed Twin 900	2025

VINs between CD0066 to CH4407
(US & CA markets only)

Triumph Motorcycles has initiated a voluntary safety recall affecting a specific VIN range of the above-referenced model. We require your immediate attention to rectify the above machines.


WHAT IS THE PROBLEM?

The red rear turn signal indicators do not meet U.S. and Canadian lighting standards, which require a minimum separation distance of 4 inches (edge-to-edge) between the turn signals and the center tail/brake lamp when red rear turn signal lamps are used. Red turn signal indicators placed too close to the rear tail/brake lamp may affect other road users' ability to accurately assess the rider's intent, increasing the risk of a crash.

WHAT WILL TRIUMPH DO?

To address this condition, Triumph is launching a new recall as described in **Safety Recall Action Notice 630**. The remedy for this recall is to replace the red rear indicators with amber indicators, free of charge (parts and labor). Amber indicators are not subject to the separation distance requirements.

Safety Recall Action Notice 630

 SB Recall Notice 630.pdf

Notification letters to current owners will be mailed on or shortly after approval from the authorities, explaining the action and advising owners to return their bikes to a Triumph dealer to have the modification carried out free of charge.

WHAT SHOULD YOU DO?

All affected motorcycles are to be checked and, if necessary, repaired in accordance with Safety Recall Action Notice 630. **Note: the VIN search function is expected to populate with affected VINs on Triumph Online after March 11th 2025.**

It is imperative that any owner who has purchased an affected motorcycle be contacted by you immediately and asked to return the motorcycle for modification.

Triumph Dealers should take the following actions:

1. Quarantine all unsold motorcycle stock (including motorcycle stock for sale on your website and with 3rd parties) and arrange to perform the repair as per the above Safety Recall Action Notice prior to any further deliveries to customers.
2. Owners of motorcycles outside of the affected VIN range are not affected by this recall and may therefore require reassurance.
3. Using your own records, please contact affected customers to arrange repairs at the earliest opportunity.
4. This action is likely to increase visitor traffic to your showroom and service areas. Please ensure all arrangements are made to best accommodate them.

FEDERAL LAW PROHIBITS THE DELIVERY OF A RECALLED MOTORCYCLE UNDER A SALE OR LEASE UNTIL THE REMEDY HAS BEEN PERFORMED.

We apologize for the inconvenience this may cause, but we are taking this action in the interest of our customers' personal safety and satisfaction with our products. We thank you in advance for your anticipated cooperation.

If you have any questions, please contact Triumph Customer Support at (888) 284-6288.