



Recall Information Bulletin

No: C10135 Issued: 7/31/2025

NHTSA No: 25V215

Transport Canada No: N/A

SUBJECT:

Safety Recall C10135 – Headlight Sockets

MODELS:

FEC7K (E16L/E16M), FEC9K (E18L/E18M)

VEHICLES INVOLVED:

Certain 2024 model year FEC7K and FEC9K trucks.

A list of vehicles your Dealership has sold that require this Recall can be found on the “Open Campaigns” list supplied by RIZON. Some individual vehicles described above may not need the Recall as the repairs may have already been performed. Always check the vehicle information section in DealerPro, or they may contact Rizon Warranty at rizonwarranty@rizontruck.us to verify that the VIN requires this Safety Recall.

Important note: It is a violation of Federal law for a dealer to deliver a new or used motor vehicle covered by this Recall Information Bulletin, under a sale or lease, until the Safety Recall has been completed.

OWNER NOTIFICATION:

Owners of affected vehicles will be notified by mail.

CONDITION:

Mitsubishi Fuso Truck of America, Inc. has decided that a defect, which relates to motor vehicle safety, exists in the headlight sockets on RIZON vehicles equipped with turn signals integrated into the headlights. As a result, there is a risk that the flasher bulb contacts of the turn signals will burn or melt due to vibrations while driving, causing the turn signals at the front of the vehicle to not illuminate. If the turn signal stops working. Trucks stop being able to signal direction when taking turns. Possibly leading to accidents caused by communication errors.

MODIFICATION:

The headlight assemblies will be replaced.

PARTS REQUIRED:

1) LT229A09EX Left side headlight assembly, 1) LT229A10EX Right side headlight assembly

RECALL CLAIM SUBMITTAL:

Upon completion of a recall or field fix repair, a warranty claim must be submitted to Rizon US through the DealerPro system or manually through our interim process. It is important to use the appropriate claim type, e.g. Recall or Field Fix and Recall/Field Fix number. The claim will be processed by Rizon and reimbursement will be completed using the reimbursement schedule used for your standard warranty claims. If you need support submitting a claim or have general claim questions, please contact Rizon US Warranty Department at rizonwarranty@rizontruck.us.

Campaign Reimbursement					
Campaign Number	Models	Allowances		Labor Description	Part Number
C1013510	FEC7K FEC9K	Labor Time	0.9 hour	Install headlight assemblies	LT229A09EX LT229A10EX

REPAIR PROCEDURE:

1. Park the vehicle on a flat, level surface, turn off the engine and chock the wheels.

CAUTION!

Do not remove the wheel chocks until all modification work has been completed.

2. Install and adjust the headlight assemblies using the procedures outlined in sections 51 and 54 of the RIZON Service Manual