

**Daimler Truck
North America LLC**

Daimler Truck North America LLC
Warranty Campaigns Department
P.O. Box 4090
Portland, OR 97208-4090
800.547.0712 Phone

DATE: 06/09/2025

TO: My Communication

SUBJECT: SAFETY RECALL NOTICE – STOP DELIVERY: F1020

On **May 19, 2025**, Daimler Truck North America (DTNA) filed a Defect Information Report (DIR) with the National Highway Traffic Safety Administration (NHTSA) and/or a Defect Information Notice (DIN) with Transport Canada (TC) informing the agencies of our intent to conduct a voluntary safety recall.

It is a violation of Federal law for a dealer or distributor to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied. **Some of the vehicles subject to this "Stop Delivery Notice" may be in your *new* vehicle inventory.** Until further instructions are available, ***new* vehicles subject to this "Stop Delivery Notice" must be held and not be delivered to customers.**

DTNA strongly recommends that dealers and distributors remedy Recalls before selling used vehicles. For any used vehicle with an open recall not remedied before sale, DTNA requires that the dealer or distributor notify prospective buyers of the open recall.

Please ensure that registration information on vehicles subject to this recall is up to date to facilitate accurate owner notification.

Affected Vehicles in F1020:

Make	Model	Model Yr. Start	Model Yr. End	Prod. Start Date	Prod. End Date
Western Star	47X	2021	2026	July 8, 2020	May 14, 2025
Western Star	49X	2020	2026	March 19, 2019	May 14, 2025

Problem: A defect, which relates to motor vehicle safety, exists in certain model year 2020-2026 Western Star 47X and 49X vehicles with a positive junction point stud that connects the battery and/or auxiliary power distribution to starter at the frame rail which may have been installed incorrectly. If the positive junction point stud was installed incorrectly this can result in a short circuit increasing the risk of a thermal event or vehicle fire.

Owner Notification Mailing Schedule: 07/18/2025