

[Next Unread Message](#)

**View Message**

<b>Sent on</b>	06	03	2025	<b>Expires on</b>	08	30	2025
<b>From</b>	PS&P Service Communications						
<b>Subject</b>	STOP SALE NOTICE UPDATE: MULTI MODEL - Sealing Bolt Oil Leak SAFETY RECALL						

June 3, 2025

Re: **STOP SALE NOTICE UPDATE: Sealing Bolt Oil Leak SAFETY RECALL**

**This bulletin has been revised to include the MY2024 XL750 Transalp model**

Dear Honda Dealer:

Honda is issuing a **STOP SALE NOTICE** on CERTAIN 2025 CB750, 2024 and 2025 XL750 TRANSALP, 2024 and 2025 CMX1100 Rebel, 2025 CRF1100 Africa Twin, and 2025 NT1100 motorcycles with manual transmissions to inspect the oil pressure switch sealing bolt for oil leaks. Due to a manufacturing defect, the sealing bolt was improperly machined, causing engine oil to leak past the bolt. If the motorcycle continues to operate with an oil leak, oil can splash onto the rear tire, resulting in a loss of traction and potentially increasing the risk of a crash or injury.

**Effective immediately, you MUST NOT SELL any affected NEW or USED 2025 CB750, 2024 and 2025 XL750, 2024 and 2025 CMX1100, 2025 CRF1100, and 2025 NT1100 motorcycle until it is repaired, according to the associated Service Bulletin. Additionally, you MUST NOT SELL or INSTALL any affected 22 mm sealing bolt with P/N 90048-MFL-000.**

**AFFECTED UNITS**

**CERTAIN NEW or USED 2025 CB750, 2024 and 2025 XL750, 2024 and 2025 CMX1100, 2025 CRF1100, and 2025 NT1100 motorcycle: ALL 22 mm sealing bolts with a P/N 90048-MFL-000 in dealer spare parts inventory.**

**SERVICE BULLETIN**

*Service Bulletin: Multiple Model Motorcycle #1*, which includes all the information relating to this Safety Recall, is expected to be issued in late June 2025.

**PARTS INFORMATION**

The parts needed for the repair can be ordered according to the instructions in the forthcoming Service Bulletin.

**CUSTOMER NOTIFICATION**

American Honda intends to mail customer letters to all owners of the affected **units listed above** in July 2025. The letter will inform customers that their motorcycle may be affected by a safety-related defect and advise them to make an appointment with an authorized Honda dealer for repair.

**Make sure all departments in your dealership are aware of this Safety Recall.**

If you have questions, please contact AHM TechLine through TechLine Connect on **iN**.

Sincerely,

**American Honda Motor Co., Inc.**  
Powersports Division

MTB 55354 (0525)