

[Next Unread Message](#)

**View Message**

**Sent on** 07 25 2025 **Expires on** 10 22 2025

**From** Parts, Service & Technical Division

**Subject** Safety Recall: 2023-25 Pilot Brake Pedal Pivot Pin Inspection (A25-029) REVISION

Dear Honda Service Manager,

A revised version of this Safety Recall service bulletin is now available on SIS and [attached to this message](#). The update reminds technicians **not to use power tools** when torquing the inspection tool during the procedure. Power tools can over-torque the Allen head bolts and center bolt, potentially damaging the brake pedal bracket and/or the brake inspection tool. The revision includes added text and images to highlight this important instruction. Please ensure your technicians are aware of these changes.

Best regards,

American Honda Motor Co., Inc.  
Parts, Service & Technical Division