



Service Engineering Operations  
Customer Service Division

Ford Motor Company  
PO Box 1904  
Dearborn, Michigan 48121

June 16, 2025

**TO:** All U.S. Ford and Lincoln Dealers

**SUBJECT: NEW VEHICLE DEMONSTRATION / DELIVERY HOLD Advance Notice –  
Safety Recall 25S63**  
Certain 2025 Model Year F-150 equipped with a 2.7L Engine  
Coolant Line and Engine Wire Harness Relocation

**AFFECTED VEHICLES**

Vehicle	Model Year	Assembly Plant	Build Dates
F-150	2025	Dearborn	February 17, 2025 through February 20, 2025

US population of affected vehicles: 37. Affected vehicles are identified in OASIS and FSA VIN Lists.

**REASON FOR THIS SAFETY RECALL**

In some of the affected vehicles, a contact condition may exist between the engine wiring harness and the engine coolant line, leading to chafing of the engine wiring harness or pull-out of Powertrain Control Module (PCM) connector pins. Chafing of the engine wiring harness or pull-out of PCM connector pins can result in an engine stall. An engine stall while driving increases the risk of a crash. The operator may notice illumination of the Malfunction Indicator Lamp (MIL), reduced engine power, hesitation, or other engine drivability symptoms.

**SERVICE ACTION**

DO NOT DEMONSTRATE OR DELIVER any new in-stock vehicles involved in this safety recall. **A complete Dealer Bulletin will be provided to dealers in Quarter 3 of 2025 when it is anticipated that parts ordering information including repair instructions will be available to support this safety recall.** For new vehicle storage guidelines, refer to EFC13033, Storage Guidelines for New Vehicles.

**IMPORTANT: Dealers should open a Repair Order (RO) only when a full dealer bulletin is published. Opening an RO against an Awareness or Advance Notice will result in warranty rejections against a recall.**

**OWNER NOTIFICATION**

Owners of record will be notified via first-class mail within sixty days, which may occur before **parts ordering information** including repair instructions have been provided to dealers.

**PLEASE NOTE:**

**Federal law requires dealers to complete this recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to \$27,168 per vehicle. Correct all vehicles in your new vehicle inventory prior to delivery.**

**DEALER-OPERATED RENTAL VEHICLES**

The Fixing America's Surface Transportation (FAST) Act law effective June 2016 prohibits a rental company from selling, renting or leasing vehicles subject to a safety or compliance recall. Please consult your legal counsel for legal advice.

## **QUESTIONS & ASSISTANCE**

For questions and assistance, contact the Special Service Support Center (SSSC) via the SSSC Web Contact Site. The SSSC Web Contact Site can be accessed through the Professional Technician System (PTS) website using the SSSC link listed at the bottom of the OASIS VIN report screen or listed under the SSSC tab.

Customer Service Division