

SERVICE PROCEDURE

25507
August, 2025

SUBJECT: SAFETY RECALL INTERIM NOTICE

Brake systems on certain 2019 thru 2025 International® CV™ Series trucks built 1/11/2018 thru 9/9/2024, manufactured without a silicone block harness, with feature codes 0004198, 0004240 (Brake system, hydraulic with Hydromax brake booster).

CUSTOMER LETTER

Print ready (PDF file) copy of the [Customer Letter](#)

DEFECT DESCRIPTION

These vehicles may have been built with a brake pressure switch assembly that allows brake fluid to leak beyond the diaphragm seal into the pressure switch. The brake fluid may seep into the electrical components and short the brake pressure switch.

If brake fluid shorts the brake pressure switch and the associated fuse, the circuit can generate excessive heat that can result in a fire increasing the risk of property damage or personal injury to the operator.

MODELS INVOLVED

This safety recall involves certain International® CV™ Series trucks remedied under Safety Recall 23V-282 (International 23511) and manufactured without a silicone block harness, built 1/11/2018 thru 9/9/2024 with feature codes 0004198, 0004240 (Brake system, hydraulic with Hydromax brake booster).

ELIGIBILITY

This procedure applies ONLY to vehicles marked in the International® Service PortalSM with Safety Recall **25507**. Also complete any other open campaigns listed on the Service Portal at this time.

ACTIONS YOU SHOULD TAKE

NOTE: Until the remedy can be performed, vehicle owners are advised to park their vehicles outdoors.

- A final remedy has been determined. Parts are on order, but availability is currently unknown. A second notice will be sent to you, once the free remedy is available.

**International Motors, LLC* International Motors,
LLC d/b/a International Motors USA LLC in Illinois
and Ohio.**