

ASA7 Recall campaign/ Stop Delivery - Check screw connection for airbag in front seats and rework if necessary

ASA7 Recall campaign/ Stop Delivery - Check screw connection for airbag in front seats and rework if necessary

Important Information

PORSCHE CENTERS SHOULD NOT SELL, LEASE, RENT, OR LOAN ANY NEW OR USED VEHICLES IN DEALER INVENTORY AFFECTED BY THIS NOTIFICATION PRIOR TO REMEDY. PORSCHE CENTERS GROUNDING LEASE RETURNS SHOULD REMEDY ALL AFFECTED GROUNDED VEHICLES.

Any vehicles delivered to customers before this announcement may be released from Stop Delivery by sending a PRMS Warranty / Campaigns Ticket to PCNA_Warranty_Support in PRMS. The ticket must have proper documentation of the sale / delivery.

ID Number	ASA7
Affected Models	Macan Electric (XAB)
Affected Model Years	2024-2025
VIN List	Attached below
Number of Affected Vehicles	3
Issue Description	Due to an isolated assembly deviation, the front seat-mounted airbag assemblies in 3 specifically identified vehicles need to be inspected.
What should Porsche Centers do?	Please arrange for the remedy to be carried out on affected vehicles as soon as possible. The remedy is immediately available as of 8/20/25.
What will Porsche do?	Vehicles will have the remedy carried out as soon as available. The remedy is immediately available as of 8/20/25.
Technical Information	ASA7
Parts Status	Status 0 - No parts required.

ASA7 Recall campaign/ Stop Delivery - Check screw connection for airbag in front seats and rework if necessary

Customer Letter

To be posted at a later date.

Customer Reactive Statement

Based on production records, Porsche identified 3 vehicles that require an inspection of the front seat-mounted airbag assemblies. Affected customers are being notified and the remedy will be conducted free of charge.

Warranty Processing

Please enter the campaign carried out in the Warranty and Maintenance booklet for the vehicle.

Scope 1-7: Check screw connection securing side airbag or center airbag to front seat

Damage number	ASA7 99 000
Repair code	1
Labor time	47 TU - 63TU

Scope 8-14: Rework screw connection securing side airbag or center airbag to front seat

Damage number	ASA7 99 000
Repair code	1
Labor time	51 TU - 67TU

Attachments

1. [VIN_List_Report_ASA7_2025-08-20_V3.xlsx](#)