

**Recall 25V-497 (Flat Rate 900009/900009A) CAN 2025-402  
Model Z Under Floor Wiring**

It has been decided that the vehicles in the recall population were assembled without the standard wire harnesses utilized by Brinkley RV. In place of the wiring harness, individual wires were ran in the recalled units. In certain circumstances, these individual wires may migrate below holding tanks, creating a pinch point between the tanks and underlying support members. The remedy is to inspect, and if necessary, secure/repair under floor wiring. Brinkley RV will pay for the Campaign to be completed. There is no charge to you for the remedy.

This recall affects a total of 40 vehicles.

Model Z VIN Range [REDACTED]

**NOTICE**

**IT IS A VIOLATION OF FEDERAL LAW FOR A DEALER TO SELL OR LEASE ANY  
NEW VEHICLES IN DEALER INVENTORY COVERED BY THIS NOTIFICATION  
UNTIL THE VEHICLE HAS BEEN REPAIRED.**