

D027 – RANGE ROVER (L405) FRONT SUSPENSION KNUCKLE CRACK – PHASE 3 SAFETY RECALL



AFFECTED MODELS	15-17MY Range Rover
VOLUME AFFECTED	37,961 US 3,343 CAN
REPAIR	A concern has been identified on certain Range Rover vehicles where the front suspension upper knuckle joint could develop a crack. In extreme cases where a crack in the front suspension knuckle has developed, this may lead to detachment of the upper suspension arm. Affected vehicles will require inspection for cracks and either the replacement of the suspension knuckle casting, or the addition of a supporting bracket.
REPAIR TIME	Between 0.8 and 1.9 hrs + DIDO
CAMPAIGN LAUNCH	<p>Retailer administration bulletin D027ADM1 was published on August 15th, 2025. Recall repairs will now be split into 3 phases which will be launched as parts supply permits.</p> <p>N759 (Phase 1) – 10,018 US 549 CAN – Repair launched on August 15th, 2025 D041 (Phase 2) – 6731 US 0 CAN – Repair launched on November 7th. D027 (Phase 3) – 37961 US 3343 CAN - Repair launched on April 17th</p>
NOTES	For D027 - Refer to Customer Service Parts Bulletins, 262704.033, USA and JLRCS-2026.04.04, Canada - for details on Retailer automatic parts shipments.