

SAFETY RECALL - FRONT STEERING KNUCKLE CRACKING REVISED POPULATION USA

SAFETY RECALL – FRONT KNUCKLE CRACKING - USA	
AFFECTED MODELS	14-17MY Range Rover
VOLUME AFFECTED	Revised affected Volume 54,720 USA
REPAIR	A concern has been identified on certain Range Rover vehicles where the front suspension upper knuckle joint could develop a crack. In extreme cases where a crack in the front suspension knuckle has developed, this may lead to detachment of the upper suspension arm. Affected vehicles will require inspection for cracks and either the replacement of the suspension knuckle casting, or the addition of a supporting bracket.
REPAIR TIME	Between 0.8 and 1.9 hrs + DIDO
CAMPAIGN LAUNCH	USA vehicles were originally announced as part of existing Canadian Recall N759. Given the recent significant increase in the affected population and increased parts demand recall USA repairs will now be split into 3 phases 1 st phase approx. 10,018 vehicles. Target launch w/c August 11 th , 2025 2 nd and 3 rd phases - launch timing to be finalized based on part supply lead times.
NOTES	Further details on the phased launch are being developed and will be shared by bulletin and presented in a future TUCC.