

D027V3 – RANGE ROVER FRONT SUSPENSION KNUCKLE CRACK

- **Bulletin Update:**
 - Revised with additional service instructions and updated warranty claim procedures
- **Key Changes:**
 - New guidance applies if steering knuckles with part prefix “DPLA” are identified during inspection
 - **No longer required** to contact JLRCAMP for these cases
 - New option codes to cover DPLA related part’s
- **Vehicle Applicability:**
 - Certain 2015-2017 MY Range Rover vehicles
 - Part of the 3rd phase of steering knuckle recall actions
 - Previous phases:
 - N759
 - D041
- **Warranty Guidance:**
 - Use updated warranty claim procedures outlined in this version
 - Pay attention toward DPLA parts handling and claim process changes
 - Confirm recall closure and documentation accuracy for audit compliance