

D019 – RANGE ROVER SPORT (L494) FRONT SUSPENSION KNUCKLE CRACK SAFETY RECALL



AFFECTED MODELS	14-17MY Range Rover Sport
VOLUME AFFECTED	66,789 US 9,239 CAN
REPAIR	A concern has been identified on certain Range Rover Sport vehicles where the front suspension upper knuckle joint could develop a crack. In extreme cases where a crack in the front suspension knuckle has developed, this may lead to detachment of the upper suspension arm. Affected vehicles will require inspection for cracks and either the replacement of the suspension knuckle casting, or the addition of a supporting bracket.
REPAIR TIME	Between 0.8 and 1.9 hrs + DIDO
CAMPAIGN LAUNCH	Retailer administration bulletin D019ADM1 was published on August 15 th , 2025. Repair publication is forecast for end of May 29 th , 2026, based on parts supply plans.
NOTES	Please review the content in the administration bulletin and follow all instructions relating to unsold vehicles in retailer inventory. Until these recall repairs are published, if a client presents a vehicle that is open in this recall and is diagnosed with a cracked knuckle, retailers should replace cracked knuckles using current parts. The repair should be submitted through the goodwill calculator and escalated for manual review.