



# HUSQVARNA TECHNICAL BULLETIN HTB25xx – USA

SEPTEMBER xx, 2025

## RECALL INTERIM NOTICE

## STOP VEHICLE SALE NOTICE

### E-THROTTLE ASSEMBLY REPLACEMENT

#### AFFECTED MODELS:

**2022 401 SVARTPILEN**

**2022 401 VITPILEN**

**2023 401 SVARTPILEN**

**2023 401 VITPILEN**

#### RESTRICTIONS: AFFECTED MODELS ARE LINKED BY VIN IN DEALER.NET

**THE REMEDY FOR THIS RECALL IS NOT YET AVAILABLE. YOU WILL RECEIVE ANOTHER TECHNICAL BULLETIN ON THIS TOPIC AS SOON AS THE RECALL REPAIR IS AVAILABLE AND CAN BE COMPLETED ON AFFECTED MOTORCYCLES**

#### BASIC INFORMATION:

Husqvarna Mobility North America, Inc. has determined that a defect which relates to motor vehicle safety exists with certain 2022 and 2023 401 SVARTPILEN and 401 VITPILEN motorcycles.

On certain motorcycles, water could enter the throttle (e-throttle) control unit and cause it to fail. If this happens, the engine will return to idle.

A loss of engine power could increase the risk of an accident.

To ensure the highest level of safety, performance, reliability and customer satisfaction, it is necessary to replace the e-throttle assembly on all affected motorcycles.

Due to the replacement e-throttle assembly not being available the e-throttle assembly replacement on affected motorcycles can't be performed at this time.

Once e-throttle assemblies are available, you will receive another technical bulletin on this topic as soon as e-throttle assemblies are available to order to complete the e-throttle assembly replacement on affected motorcycles.

#### COPYRIGHT NOTICE

The user acknowledges that all components of this technical information are Husqvarna's and/or third parties' copyright protected property. Alteration, assignment, distribution and reproduction are forbidden.

#### LIMITATION OF LIABILITY

The information included in or available through this technical information may include inaccuracies or errors. In no event shall Husqvarna and/or its suppliers be liable for any damages whatsoever, arising out of or in connection with the use of this technical information. Please always refer to the Husqvarna owners and repair manuals for proper instructions or contact the Husqvarna Dealer Services Department. ©2025 Husqvarna Mobility North America, Inc. – All rights reserved

**Husqvarna Mobility North America, Inc.**  
30125 KTM Way | Murrieta, CA 92563  
1119 Milan Ave. | Amherst, OH 44001  
8701 Samuel-Hatt | Chambly, QC, J3L 6V4

**Dealer Services Department**  
P: 855- 282-1054  
[www.husqvarna-motorcycles.com](http://www.husqvarna-motorcycles.com)



In the interim, Husqvarna Mobility North America, Inc. will be notifying all registered owners of the above affected motorcycles by mail of this recall. A copy of the customer letter is included in this bulletin.

Registered owners will also be informed again by mail to contact an authorized Husqvarna motorcycles dealer to schedule the replacement of their e-throttle assembly when the part is available.

Dealers must immediately stop selling the affected motorcycles listed above. Vehicles will be locked out from retail registration in Dealer.net until the remedy is available and performed.

It is a violation of Husqvarna Mobility North America, Inc. policy for an authorized Husqvarna motorcycles dealer to deliver any affected units to customers before the procedure in this bulletin has been performed.

For any inquiries related to this bulletin, please contact the Dealer Services department.

**COPYRIGHT NOTICE**

The user acknowledges that all components of this technical information are Husqvarna's and/or third parties' copyright protected property. Alteration, assignment, distribution and reproduction are forbidden.

**LIMITATION OF LIABILITY**

The information included in or available through this technical information may include inaccuracies or errors. In no event shall Husqvarna and/or its suppliers be liable for any damages whatsoever, arising out of or in connection with the use of this technical information. Please always refer to the Husqvarna owners and repair manuals for proper instructions or contact the Husqvarna Dealer Services Department. ©2025 Husqvarna Mobility North America, Inc. – All rights reserved

Husqvarna Mobility North America, Inc.  
30125 KTM Way | Murrieta, CA 92563  
1119 Milan Ave. | Amherst, OH 44001  
8701 Samuel-Hatt | Chambly, QC, J3L 6V4

Dealer Services Department  
P: 855-282-1054  
www.husqvarna-motorcycles.com



## IMPORTANT SAFETY RECALL NOTICE (Interim Notice) NHTSA Recall No. XX-XXXX

This notice applies to your motorcycle, VIN: «Vin»  
«PdiFirstName» «PdiLastName»  
«PdiAddress1»  
«PdiCity», «PdiProvince» «PdiPostalCode»

9/xx/2025

**RE: Affected models:**  
**2022 401 SVARTPILEN**  
**2022 401 VITPILEN**  
**2023 401 SVARTPILEN**  
**2023 401 VITPILEN**

Dear Husqvarna motorcycle customer,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Husqvarna Mobility North America, Inc. has determined that a defect which relates to motor vehicle safety exists with certain 2022 and 2023 401 SVARTPILEN and 401 VITPILEN motorcycles.

On certain motorcycles, water could enter the throttle (e-throttle) control unit and cause it to fail. If this happens, the engine will return to idle.

A loss of engine power could increase the risk of an accident.

To ensure the highest level of safety, performance, reliability and customer satisfaction, it is necessary to replace the e-throttle assembly on all affected motorcycles.

The remedy for this recall is not yet available due to the replacement e-throttle assembly not being available. Therefore the e-throttle assembly replacement on affected motorcycles can't be performed at this time.

Once e-throttle assemblies are available, you will be informed again by mail to contact an authorized Husqvarna motorcycles dealer to schedule the replacement of the e-throttle assembly on your motorcycle.

If you have any questions related to the content of this letter, please contact Husqvarna Mobility North America, Inc. Customer Relations at (888) 985-6090 for assistance. Furthermore, if for any reason Husqvarna motorcycles is unable to remedy the situation without charge, or within a reasonable amount of time, you may write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590 or call 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.nhtsa.gov>

We apologize for any inconvenience and want to assure you that our commitment together with all Husqvarna Dealers is to provide you with the highest level of service, support and customer satisfaction.

Best Regards,  
Dealer Services Department  
Husqvarna Mobility North America, Inc.

#### COPYRIGHT NOTICE

The user acknowledges that all components of this technical information are Husqvarna's and/or third parties' copyright protected property. Alteration, assignment, distribution and reproduction are forbidden.

#### LIMITATION OF LIABILITY

The information included in or available through this technical information may include inaccuracies or errors. In no event shall Husqvarna and/or its suppliers be liable for any damages whatsoever, arising out of or in connection with the use of this technical information. Please always refer to the Husqvarna owners and repair manuals for proper instructions or contact the Husqvarna Dealer Services Department. ©2025 Husqvarna Mobility North America, Inc. – All rights reserved