

- [📄 25-01-085H - LX2 Front-Rear Seat Belt Buckle Replacement \(Recall 283\) \(posted 11.24.25\).pdf](#)
- [📄 Recall 283 - Parts Bulletin Initial Shipment & Ordering \(posted 11.24.25\).pdf](#)
- [📄 Recall 283 - Seat Belt Buckle Assembly - Dealer Notification \(Remedy\) \(posted 11.24.2025\).pdf](#)

Hyundai Motor America (HMA) has launched Remedy Available for Recall 283 – First & Second Row Seat Belt Buckle Replacement.

A "stop sale" has been issued on affected new vehicles in dealer's inventory. As required by federal law, dealers must not deliver new vehicles for sale or for lease to customers until all open recalls have been performed. Dealers must perform all open recalls on used vehicles, demo, and rental vehicles prior to placing them into customer use and whenever an affected vehicle is in the shop for any maintenance or repair.

A. Affected Vehicles:

- Certain 2020-25MY Palisade (LX2) vehicles produced 04/10/2019 – 06/16/2025 built by Hyundai Motor Company ("HMC")
- VIN Identification: Use the 'Vehicle Information' screen in WebDCS under the 'Campaign Not Performed' section to determine recall applicability.

B. Recall Description:

Certain Palisade (LX2) vehicles are equipped with seat belt buckle assemblies in the front row and second row outer seating positions that may contain out-of-specification components manufactured by the supplier. These components can cause interference within the latch channel, potentially increasing friction, particularly under cold ambient temperatures. Improperly produced seat belt buckles, combined with slow insertion of the seat belt tongue plate, may prevent the seat belt buckle from fully latching. An inability to fasten the seat belt in an occupied seat could increase the risk of injury to occupant(s) during a crash. Follow the information **Technical Service Bulletin (TSB) 25-01-085H** to replace the outer seat belt buckle assemblies.

C. New Stock Vehicles at Dealers:

- 3,067 – Divided by region as noted below – 3,065 at dealers & 2 in-transit to dealers.

Recall 283 Dealer Stock		
Region	PALISADE	
CE	181	
EA	549	
MA	68	
MS	358	
SC	744	
SO	380	
WE	787	
Other (NH, NL)	0	
Total	3,067	

D. Parts Information

1. Recall 283 Parts Bulletin

- Available on Hyundaiadealer.com > Parts > Documents Library > Reference Materials > Parts Bulletins

2. Initial Shipment

a. New Vehicle Inventory & SRCs (RC283S8500QQH):

Dealers have been shipped parts for new stock vehicles & SRCs identified in their inventory as of 11/24/25.

- i. If a dealer was not identified to have any used vehicles, they were shipped one (1) part.
- ii. Please see counts and quantities to be shipped to reach dealer Dealer Order # RC283A.
- iii. Parts are expected to arrive starting at dealers tomorrow, 11/25/25.

b. Used Vehicle Inventory (RC283S8000QQH): Dealers will be shipped parts for used vehicles identified in their inventory as of 11/24/25.

- i. If a dealer was not identified to have any used vehicles, they were shipped one (1) part.
- ii. **Parts are expected to arrive starting at dealers on Wednesday, 11/26/25.**

E. Campaign Documents:

1. TSB 25-01-085H

a. Available on Hyundaidealer.com > Service > HMA Tech Info > Campaign

2. Dealer Notification

Available on Hyundaidealer.com > Service > HMA Tech Info > Service News

F. Action Required:

1. Confirm VIN eligibility via WebDCS. Review if any vehicles are currently at dealer's location in dealer stock. **Do not sell any vehicles identified with an open recall until remedy has been applied.**
2. **Follow TSB 25-01-085H** to perform the service procedure to replace the seat belt buckles.
3. **Submit campaign claim** once the service procedure is completed.

We appreciate your continued partnership and commitment to our Hyundai customers regarding this safety matter. Thank you for your patience and understanding.

Warranty Campaign Team
Hyundai Motor America