



ADVANCE DEALER NOTICE OF SAFETY RECALL

DATE	9/26/2025
RECALL ID	Kia: SC351 / NHTSA: TBD
SUBJECT	Kia is conducting a safety recall to address an issue involving the HVAC wire harness.
AFFECTED VEHICLES	All 2021-2023 MY Sorento LX vehicles (S, EX, SX and X-line models are not affected)
AFFECTED POPULATION	Approximately 39,536 vehicles
RECALL CONDITION	Due to a suspected wire harness supplier quality issue, the connection between the blower motor resistor and connector can overheat when using the HVAC system on fan speed 3 while the ignition is on. In rare cases, this condition may lead to a fire, increasing the risk of injury.
REMEDY	Replace, as a set, both the blower motor resistor circuit harness with an improved one and blower motor resistor with a new one
REMEDY AVAILABILITY	REMEDY PART IS NOT YET AVAILABLE.
PLANNED NOTIFICATIONS	Dealers will be notified in writing on 11/20/2025. Owners will be notified by first-class mail on 11/24/2025.
NHTSA ADVISORY	It is a violation of Federal law for a dealer to deliver a new motor vehicle covered by this notification under a sale or lease until the defect is remedied.

If you have any questions, please contact your Kia District Parts and Service Manager.

Sincerely,

Kia North America Safety Office