



Service Engineering Operations  
Customer Service Division

Ford Motor Company  
PO Box 1904  
Dearborn, Michigan 48121

October 14, 2025

**TO:** All U.S. Ford and Lincoln Dealers

**SUBJECT: NEW VEHICLE DEMONSTRATION / DELIVERY HOLD - Advance Notice  
Compliance Recall 25C53**  
Certain 2024-2025 Model Year Lincoln Corsair  
Rear Combination Lamp Inspection/Replacement

**AFFECTED VEHICLES**

Vehicle	Model Year	Assembly Plant	Build Dates
Corsair	2024	Louisville	December 15, 2023 through February 12, 2024
	2025		January 31, 2025 through August 15, 2025

US population of affected vehicles: 84 Affected vehicles are identified in OASIS and FSA VIN Lists.

**REASON FOR THIS COMPLIANCE RECALL**

Some of the affected vehicles may not conform to the requirements specified by Federal Motor Vehicle Safety Standard (FMVSS) No. 108, Lamps, reflective devices, and associated equipment. The left or right Rear Combination Lamp (RCL) may have been damaged during vehicle assembly, which may allow water leakage into the lamp. This could result in inoperative exterior lamp functions, including the backup lamp, stop lamp, and tail lamp. Loss of these lighting functions reduces the vehicle's visibility and may not fully alert other drivers that the vehicle is braking, turning, or reversing, increasing the risk of a crash.

**SERVICE ACTION**

DO NOT DEMONSTRATE OR DELIVER any new in-stock vehicles involved in this compliance recall. For new vehicle storage guidelines, refer to EFC13033, Storage Guidelines for New Vehicles.

**A complete Dealer Bulletin will be provided to dealers in November 2025 when it is anticipated that a remedy, including repair instructions, will be available to support this compliance recall.**

**IMPORTANT: Dealers should open a Repair Order (RO) only when a full dealer bulletin is published. Opening an RO against an Awareness or Advance Notice will result in warranty rejections against a recall.**

**OWNER NOTIFICATION**

Owners of record will be notified via first-class mail within sixty days, which may occur before remedy availability, including repair instructions, have been provided to dealers.

**PLEASE NOTE:**

**Federal law requires dealers to complete this recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to \$27,168 per vehicle. Correct all vehicles in your new vehicle inventory prior to delivery.**

### **DEALER-OPERATED RENTAL VEHICLES**

The Fixing America's Surface Transportation (FAST) Act law effective June 2016 prohibits a rental company from selling, renting or leasing vehicles subject to a compliance recall. Please consult your legal counsel for legal advice.

### **QUESTIONS & ASSISTANCE**

For questions and assistance, contact the Special Service Support Center (SSSC) via the SSSC Web Contact Site. The SSSC Web Contact Site can be accessed through the Professional Technician System (PTS) website using the SSSC link listed at the bottom of the OASIS VIN report screen or listed under the SSSC tab.

Customer Service Division