

**From:** [JLRNA Customer Service Publications](#)  
**To:** [n1wq0l1udz@jlrdemo.netlink.com](mailto:n1wq0l1udz@jlrdemo.netlink.com)  
**Cc:** [um-nsc-usa-jag-alerts](#)  
**Subject:** RE: Safety Related Recall H566- Transmission Control Switch (TCS) Moisture Ingress  
**Date:** Tuesday, March 10, 2026 11:51:18 AM

---

**TO: Jaguar Authorized Retailer Aftersales Personnel**

**Retailers are advised the two vehicles detailed below that are included in Safety Recall H566 have both been repaired prior to wholesale and now show H566 as closed in the Warranty portal. No action is required by any US Retailer.**

- **Safety Related Recall – H566ADM1 – Administration Bulletin - Transmission Control Switch (TCS) Moisture Ingress.**

This bulletin was published on TOPIx and affects the following two (2) 2026MY USA F-PACE vehicles.

SADCT2FU2TA760850

SADCT2FU6TA760852

A concern has been identified where it is possible that moisture has entered the Gear Selector Module during the assembly process. Under certain conditions there is a risk that this moisture could result in a lack of Light Emitting Diode (LED) illumination of the selected gear adjacent to the selector lever, which would not conform to regulated requirements for automatic transmission control position indicator illumination.

**PLEASE DO NOT REPLY TO THIS EMAIL.**

CUSTOMER SERVICE PUBLICATION



Jaguar Land Rover North America LLC, 100 Jaguar Land Rover Way, Mahwah, NJ 07495

CONFIDENTIALITY NOTICE: The email message including attachments is intended only for the person to whom it is addressed and may contain confidential information. Any unauthorised review, use, or disclosure is prohibited. If you are not the intended recipient, please contact the sender by reply email and destroy all copies of the original message.

