

Content Id: 15434

GENERAL MOTORS

DCS7377

URGENT - DISTRIBUTE IMMEDIATELY

Date: November 6, 2025

Subject: N252530830 (Both Sides), N252530831 (Left Side),
N252530832 (Right Side) - Safety Recall

Roof Rail Airbag Inflator May Rupture

Models: 2014 Buick Verano

2014 Chevrolet Cruze

General Motors is releasing Safety Recalls N252530830 (Both Sides), N252530831 (Left Side), and N252530831 (Right Side) today.

What Should Dealers Do: Dealers should review IVH, or the Dealer Maxis reports for open VINs in their inventory. Dealers can view the attached bulletins, and they will also be displayed in Service Information tomorrow.

A Stock VIN list is not included as our records show there are no vehicles in dealer new inventory.

For dealers with involved vehicles, a listing has been prepared and will be available through GM Global Connect Maxis Field Action Reports or GWM Field Action Batch Search Report. The Inventory tab of the dealer reports will contain VINs that apply to this field action. This information is intended to assist dealers with the **PROMPT COMPLETION** of these vehicles. The Customer In-Service tab will contain customer names and addresses from Motor Vehicle Registration Records. The use of such motor vehicle registration data for any purpose other than follow-up necessary to complete this field action may be a violation of law in several states.

END OF MESSAGE