



Service Engineering Operations
Customer Service Division

Ford Motor Company
PO Box 1904
Dearborn, Michigan 48121

December 3, 2025

TO: All U.S. Ford and Lincoln Dealers
SUBJECT: **NEW VEHICLE DEMONSTRATION / DELIVERY HOLD - Advance Notice
Compliance Recall 25C66**
Certain 2025 Model Year Navigator Vehicles
Reversing Lamp Assembly Replacement

AFFECTED VEHICLES

Vehicle	Model Year	Assembly Plant	Build Dates
Navigator	2025	Kentucky	August 06, 2025 through August 26, 2025

US population of affected vehicles: 1186. Affected vehicles are identified in OASIS and FSA VIN Lists.

REASON FOR THIS COMPLIANCE RECALL

Some of the affected vehicles may not conform to the requirements specified by Federal Motor Vehicle Safety Standard (FMVSS) 108 - Lamps, reflective devices, and associated equipment. The liftgate reversing lamp assembly's outer lens and/or weld track may have cracked in some of the affected vehicles. These cracks may result in a leak path, allowing water intrusion into the lamp assembly, leading to internal electronics failure over time and inoperative or flickering backup lamp function. Vehicles with inoperative or flickering backup lamp(s) can increase the risk of a crash.

SERVICE ACTION

DO NOT DEMONSTRATE OR DELIVER any new in-stock vehicles involved in this compliance recall. For new vehicle storage guidelines, refer to EFC13033, Storage Guidelines for New Vehicles.

A complete Dealer Bulletin including repair instructions will be provided to dealers when a remedy is available to support this compliance recall.

IMPORTANT: Dealers should open a Repair Order (RO) only when a full dealer bulletin is published. Opening an RO against an Awareness or Advance Notice will result in warranty rejections against a recall.

OWNER NOTIFICATION

Owners of record will be notified via first-class mail after remedy availability including repair instructions have been provided to dealers.

PLEASE NOTE:

Federal law requires dealers to complete this recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to \$27,168 per vehicle. Correct all vehicles in your new vehicle inventory prior to delivery.

DEALER-OPERATED RENTAL VEHICLES

The Fixing America's Surface Transportation (FAST) Act law effective June 2016 prohibits a rental company from selling, renting or leasing vehicles subject to a compliance recall. Please consult your legal counsel for legal advice.

QUESTIONS & ASSISTANCE

For questions and assistance, contact the Special Service Support Center (SSSC) via the SSSC Web Contact Site. The SSSC Web Contact Site can be accessed through the Professional Technician System (PTS) website using the SSSC link listed at the bottom of the OASIS VIN report screen or listed under the SSSC tab.

Customer Service Division