

MACK TRUCKS RECALL ALERT



Subject: Safety Recall SC0491 Brake Chamber Inspection
Recall Number: SC0491
Date:
Applicable Markets: U.S. Canada Mexico Export

Description

Mack Granite (GU) vehicles that completed Mack recall SC0398 (15V804) may have had incorrect brake chambers installed during subsequent repairs after the recall was completed due to inaccurate dealer service information. Incorrect brake chambers can result in a brake imbalance between the steer and drive axle brakes. If an imbalance exists, the brakes may overheat which increases the risk of a tire blowout or wheel-end fire.

Model and Model Years Affected

Certain Granite (GU) model vehicles manufactured from 09/17/2009, through 07/31/2015.

Vehicle Quantities

711 vehicles (679 US, 1 Canada and 31 Export)

Dealer Responsibilities

The National Traffic and Motor Vehicle Safety Act and Canadian Motor Vehicle Safety Act require dealers to ensure that all new and used vehicles are free of safety defects and comply with all relevant safety standards at the time of delivery to the consumer.

Dealers should make their personnel aware of the safety recall. In the event that a dealer has a vehicle included in the safety recall in their inventory to be sold, the condition must be corrected before releasing it to a customer.

Notification Release Schedule

- Vehicle list will be posted on the Trucks Dealer Portal 12/22/2025.
- Owner notification letters will be released on or before 2/02/2026.
- Repair Instruction will be released once they are available.

Contact

If you have questions or concerns about this recall, contact the Regulatory Affairs Department at vtna.regulatoryaffairs@volvo.com.