

December 19, 2025

Re: **STOP SALE NOTICE: CBR650R #1 - WIRE HARNESS SHORT CIRCUIT**

Dear Honda Dealer:

Honda is issuing a **STOP SALE NOTICE** for **ALL 2024–2025 CBR650R/RA** motorcycles. Due to an assembly error, the turn-signal switch wiring harness was routed too close to the stay for left middle cowl, and normal vibrations can wear through the insulation, exposing the copper wires and cause a short circuit. A shorted harness can cause a fuse to blow, which can prevent the operator from activating the turn signals, brake lights, hazard lights, license-plate light, horn, and gauge cluster, increasing the risk of a crash or injury.

IMPORTANT: The repair procedure provided in the service bulletin only applies to NEW, unregistered units in dealer inventory. Parts and repair information for USED dealer inventory or

registered, in-service customer units will be provided in a forthcoming service bulletin revision.

Dealers will be notified by **iN** message.

AFFECTED UNITS

All 2024 and 2025 CBR650R motorcycles:

- To search for applicable recalls on a specific unit, you **MUST** use *Unit Information* on **iN**, available December 19, 2025.
- To manage your affected inventory, use your dealer *eResponsibility Report* on **iN**, available December 20, 2025.

SERVICE BULLETIN

CBR650R #1, which includes all the information relating to this Safety Recall for USED dealer inventory and in-service, registered customer units, is expected to be issued in mid-January 2026.

CUSTOMER NOTIFICATION

American Honda intends to mail customer letters to all owners of affected motorcycles in February 2026. Customers will be informed that their motorcycle is affected by this safety-related defect and that they should make an appointment with an authorized Honda dealer to have their unit repaired.

Make sure all departments in your dealership are aware of this Safety Recall.

Sincerely,

American Honda Motor Co., Inc.

Powersports Division