



Triumph Motorcycles America Ltd.
1070 White Street SW
Suite B
Atlanta, Georgia 30310

21 March 2025

! IMPORTANT SAFETY RECALL !

REAR TURN SIGNAL INDICATORS REPLACEMENT

Safety Recall: SRAN630
NHTSA Recall: 25V141

This notice applies to your motorcycle:
Model: (2025) Speed Twin 900, 1200 and 1200 RS
VIN: SMTXXXX

Dear [NAME]:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Triumph Motorcycles Ltd. has decided that certain Model Year 2025 Speed Twin 900, 1200 and 1200 RS motorcycles fail to conform to Federal Motor Vehicle Safety Standard (FMVSS) No. 108, *Lamps, reflective devices, and associated equipment*. Your motorcycle, with the VIN shown above, is affected. Triumph is conducting a safety recall to address the condition.

The reason for this recall notice: The red rear turn signal indicators on your motorcycle do not meet the federal lighting standard, which requires a minimum separation distance of 4 inches (edge-to-edge) between the turn signals and the center tail/brake lamp when red rear turn signals are used. Red turn signal indicators placed too close to the rear tail/brake light may affect other road users' ability to accurately assess the rider's intent, increasing the risk of a crash.

What Triumph Motorcycles Ltd & your dealer will do: Triumph Motorcycles Ltd has authorized your dealer to replace the rear red turn signal indicators with amber indicators, free of charge (parts and labor). This repair should take less than 30 minutes. However, depending upon the dealer's work schedule, it may be necessary to make your motorcycle available for a longer period.

What you must do to ensure your safety: Please make an appointment with your authorized Triumph motorcycles dealer to have this important remedy performed on your motorcycle as soon as possible.

Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within 10 days.

If you need help: Please contact your authorized Triumph dealer should you have any questions or encounter any difficulty regarding this recall. In the event your dealer is unable to remedy your motorcycle in a satisfactory manner, please contact Triumph Motorcycles America at 1-678-854-2010.

If an authorized Triumph dealer or Triumph Motorcycle America Ltd, fails or is unable to perform this remedy without charge within a reasonable amount of time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue SE., Washington, D.C., 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.nhtsa.gov>.

If you no longer own the motorcycle listed above, please contact Triumph at 1-678-854-2010 and provide any information you can furnish that will assist us in locating the new owner.

We apologise for any inconvenience this may cause you. However, we have taken this course of action in the best interest of your safety and your continued satisfaction with your Triumph motorcycle. We appreciate your attention and cooperation in this important matter.

Sincerely,

Triumph Motorcycles America Ltd.