

DECEMBER 2025

**IMPORTANT SAFETY RECALL 25509**

NHTSA RECALL NO. 25V502

**THIS NOTICE APPLIES TO YOUR VEHICLE IDENTIFIED ON THE ENCLOSED CARD.**

Dear International Customer,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

International Motors, LLC\* has decided that a defect which relates to motor vehicle safety exists in certain 2018 thru 2025 International® MV® Series trucks built 10/25/2017 thru 6/24/2024, 2018 thru 2024 International® 1300 Series trucks built 11/29/2017 thru 6/14/2023 and 2018 thru 2019 International® 4300 Series trucks built 9/20/2017 thru 1/9/2019, with feature codes 0004198, 0004240 (Brake system, hydraulic with Hydromax brake booster).

**REASON FOR THIS RECALL**

The brake pressure switch may allow brake fluid to seep past the diaphragm seal into the brake pressure switch electrical connector and associated fuse which can short the switch and/or fuse.

**RISK TO MOTOR VEHICLE SAFETY**

A shorted switch or fuse may cause the circuit to generate excessive heat which can result in a fire, increasing the risk of property damage or personal injury to the operator.

**DEFECT REMEDY**

You may already have been contacted about a similar Safety Recall 23517 (NHTSA 23V-397) in 2023. Any vehicle remedied under that recall also requires this recall remedy to be performed.

Vehicles will have a new brake pressure switch/fuse harness installed that contains an anti-capillary wire that will block fluid from wicking up the copper.

The repair will be performed free of charge and take approximately 1.5 hours to complete.

**ACTIONS YOU SHOULD TAKE**

**Until the remedy can be performed, vehicle owners are advised to park their vehicles outdoors.**

If you own this vehicle, please schedule an appointment with any authorized repair center to have your vehicle repaired at no cost to you. You can find your nearest dealer by using the dealer locator at <https://www.internationaltrucks.com/dealer-locator> or by calling 1-800-448-7825; or find the nearest Love's center at <https://www.loves.com>. Love's and Speedco locations in Texas and Louisiana cannot perform warranty services.

If you have already paid for repairs prior to this notice that corrected this defect, you may be eligible for reimbursement of certain repair expenses if they occurred 09/20/2017 thru 12/31/2025. Present your original repair paperwork and proof of payment to any International® dealer and your eligibility will be reviewed. You may also submit a claim using the enclosed Request for Reimbursement card.

If you are the lessor of this vehicle, please forward a copy of this notice to the lessee within ten days to comply with federal regulations.

If you do not own this vehicle, please fill out and return mail the enclosed card so that you will not be contacted again about this recall.

**IF YOU NEED FURTHER ASSISTANCE**

If you believe that International Motors, LLC has failed to remedy the defect without charge or within a reasonable time, please follow the procedure described in the Owner Assistance Guide section in your Owner's Manual or call toll free 1-800-448-7825.

You may also submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave, SE, Washington, DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-888-275-9171); or go to <http://www.safercar.gov>.

International Motors, LLC requests your prompt attention and patience regarding the correction of this defect and apologizes for any inconvenience this may cause you.