



CR310 – Check for Correct Positioning of ABS Fuses and Corresponding Fuse Holders
 Panigale V2 MY 2025 (all versions)
 Streetfighter V2 MY 2025 - 2026 (all versions)
Safety Recall Campaign SRV-RCL-25-004



010300000100
0000001

IMPORTANT SAFETY RECALL

This notice applies to your vehicle: [REDACTED]

Date: 1/20/2026

NHTSA Recall No. 25V-838

1**1**1*****ALL FOR AADC 481

[REDACTED] VIN [REDACTED]



Subject:

Ducati Motorcycle: Panigale V2 Model Year 2025 (all versions)
Streetfighter V2 Model Year 2025 – 2026 (all versions)

NHTSA Campaign I.D. Number: 25V-838

Dealer Bulletin: SRV-RCL-25-004

Dear Ducati Owner,

This notice is sent to you in accordance with the requirements of the U.S. National Traffic and Motor Vehicle Safety Act. Ducati Motor Holding S.P.A. has decided that a defect which relates to motor vehicle safety exists in certain Ducati Panigale V2 Model Year 2025 (all versions) and Ducati Streetfighter V2 Model Year 2025 – 2026 (all versions). Our records indicate that you are the owner of a Ducati motorcycle affected by this safety recall campaign. Please take the time to read this letter and help us take the appropriate steps to ensure that your vehicle is operating properly.

What is wrong?

Ongoing product quality tests have identified a potential reversal of the ABS fuses and/or their fuse holders. This could leave the ABS pump wiring protected by the 10A fuse instead of the 25A fuse. In case of reversal, during prolonged braking with ABS intervention, the 10A fuse could blow, disabling the ABS pump functionality. This could cause the front or rear wheel to lock up due to the ABS system not functioning, resulting in loss of control of the motorcycle and increased risk of crash and/or injury.

What will Ducati do?

An official Ducati dealer will perform an inspection, and, if needed, a correction to ensure the proper positioning of the ABS fuses on the affected motorcycle free of charge. The repair will take approximately 30 minutes to complete. Service time will vary depending on dealer scheduling.



CR310 – Revise la posición correcta de los fusibles de ABS y portafusibles correspondientes

Panigale V2 modelo 2025 (todas las versiones)

Streetfighter V2 modelos 2025 - 2026 (todas las versiones)

Campaña de retiro por seguridad SRV-RCL-25-004

RETIRO POR SEGURIDAD IMPORTANTE

Esta notificación aplica para su vehículo: [REDACTED]

Retiro NHTSA N.º 25V-838

Date: 1/20/2026

[REDACTED]
NIV: [REDACTED]

Asunto:

**Motocicleta Ducati: Panigale V2 modelo 2025 (todas las versiones)
Streetfighter V2 modelos 2025 – 2026 (todas las versiones)**

Identificación de campaña NHTSA Número: 25V-838

Boletín del concesionario: SRV-RCL-25-004

Estimado propietario de Ducati:

Este aviso se envía según los requisitos de la Ley Nacional de Seguridad para vehículos automotores y tráfico de EE. UU. Ducati Motor Holding S.P.A. encontró que existe un defecto relacionado con la seguridad de vehículos automotores en ciertos Ducati Panigale V2 modelo 2025 (todas las versiones) y Ducati Streetfighter V2 modelos 2025 – 2026 (todas las versiones). Nuestros registros indican que usted es propietario de una motocicleta Ducati afectada por esta campaña de retiro por seguridad. Tómese el tiempo para leer esta carta y ayudarnos a tomar los pasos adecuados para asegurarnos de que su vehículo funciona correctamente.

¿Qué está mal?

Las pruebas de calidad del producto en curso han identificado una posible inversión de los fusibles ABS o sus portafusibles. Esto podría proteger el cableado de la bomba de ABS con el fusible de 10 A en lugar del fusible de 25 A. En caso de inversión, durante un frenado prolongado con intervención del ABS, el fusible de 10 A podría quemarse, desactivando la funcionalidad de la bomba de ABS. Esto podría provocar el bloqueo de la rueda delantera o trasera debido al mal funcionamiento del sistema ABS, lo que ocasionaría la pérdida de control de la motocicleta y más riesgo de accidente o lesiones.

¿Qué hará Ducati?

Un concesionario oficial de Ducati hará una inspección, y si es necesario, una corrección para garantizar la correcta colocación de los fusibles de ABS en la motocicleta afectada sin costo alguno. La reparación tardará aproximadamente 30 minutos en completarse. El tiempo de servicio varía dependiendo de la programación del concesionario.

Comuníquese con el centro de Servicio Ducati en su localidad tan pronto como sea posible para programar una cita para la corrección. Puede seguir usando su motocicleta para ir con el concesionario autorizado de Ducati. Evite frenados bruscos que activen el ABS. Si surge algún problema, la pantalla del panel de control le avisará con un mensaje de error del ABS.

Ducati North America
www.ducati.com

1292 Reamwood Ave.
Sunnyvale CA, 94089
Tel +1 650 933 9800



**CR310 – Check for Correct Positioning of ABS Fuses
and Corresponding Fuse Holders**
Panigale V2 MY 2025 (all versions)
Streetfighter V2 MY 2025 - 2026 (all versions)
Safety Recall Campaign SRV-RCL-25-004



020300000100
0000001

Please, contact your local Ducati Service center as soon as possible to schedule an appointment for the remedy. You may continue to use your motorcycle to reach your Ducati authorized dealer. Use caution to avoid extreme braking engaging the ABS. Should a problem arise your dash display will alert you with an ABS error message.

Do not use your motorcycle for any other journeys except to reach the Service Center.

To locate your nearest authorized Ducati dealer, please go to www.ducati.com, and select the “dealer locator” or you may call toll free from the U.S. 855-801-2716.

During this recall visit, your Ducati Service Dealer shall also check for other necessary maintenance intended to keep your motorcycle operating optimally, both at the mechanical and electronic levels. In this case, it may be necessary for the workshop to keep your motorcycle for a longer period.

Federal regulations require that any lessor receiving this recall notice must forward a copy of notice to the lessee within ten days.

Service Problem Help:

If you believe that your dealer has failed or is unable to remedy the defect without charge, or within a reasonable period of time, please contact Ducati North America Client Care at 855-801-2716.

If you still cannot obtain satisfaction:

For USA Clients:

If your dealer fails or is unable to remedy this defect without charge, or within a reasonable amount of time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave. S.E., Washington, D.C. 20590; or call the toll-free Vehicle Safety Hotline at 1- 888-327-4236 (TTY 1- 800-424-9153); or go to www.nhtsa.gov.

For Canadian Clients:

Please contact Ducati Client Care at 855-801-2716 or for additional information about the recall you, can contact Transport Canada at 1-800-333-0510.

TREAD ACT CUSTOMER REIMBURSEMENT PLAN

If you have paid for the repair described in the attached letter, and you would like to be considered for reimbursement, please contact your authorized Ducati dealer. Expenses from repair facilities outside of the authorized Ducati dealer network will be considered; however, the procedure must meet Ducati North America’s remedy for this defect, or you may still need to have the recall repair performed.



CR310 – Revise la posición correcta de los fusibles de ABS y portafusibles correspondientes

Panigale V2 modelo 2025 (todas las versiones)

Streetfighter V2 modelos 2025 - 2026 (todas las versiones)

Campaña de retiro por seguridad SRV-RCL-25-004

Para encontrar al concesionario Ducati autorizado más cercano, visite www.ducati.com, y seleccione "dealer locator" (localizador de concesionarios) o llame gratis desde EE. UU. al 855-801-2716.

Durante esta visita de retiro, el Concesionario de Servicio Ducati también comprobará si es necesario hacer otros mantenimientos para que su motocicleta siga funcionando de manera óptima, tanto mecánica como electrónicamente. En este caso, puede ser necesario que el taller se quede con su motocicleta durante más tiempo.

Las regulaciones federales exigen que cualquier arrendador que reciba este aviso de retiro envíe una copia del aviso al arrendatario en el plazo de diez días.

Ayuda del problema de servicio:

Si cree que el concesionario no ha resuelto o no puede corregir el defecto sin costo alguno, o en un plazo razonable, comuníquese con Servicio al Cliente de Ducati North America llamando al 855-801-2716.

Si aún no está satisfecho:

Para clientes de EE. UU.:

Si su concesionario no corrige este defecto sin costo alguno o en un plazo razonable, puede presentar un reclamo por escrito al Administrador, National Highway Traffic Safety Administration, 1200 New Jersey Ave. S.E., Washington, D.C. 20590 o llamar a la línea directa y sin costo de Seguridad de Vehículos al 1- 888-327-4236 (TTY 1- 800-424-9153) o visitar www.nhtsa.gov.

Para clientes canadienses:

Llame a Servicio al Cliente de Ducati al 855-801-2716 o, para obtener más información sobre el retiro, puede llamar a Transport Canada al 1-800-333-0510.

PLAN DE REEMBOLSO A CLIENTES SEGÚN LA TREAD ACT (LEY DE MEJORA DE RETIRO, RESPONSABILIDAD Y DOCUMENTACIÓN EN EL TRANSPORTE)

Si pagó la reparación que se describe en la carta adjunta y quisiera que lo tomen en cuenta para el reembolso, comuníquese con su concesionario Ducati autorizado. Tendremos en cuenta los gastos de las instalaciones de reparación fuera de la red de concesionarios Ducati autorizados; sin embargo, el procedimiento debe cumplir la solución de Ducati North America para este defecto o es posible que tenga que realizar la reparación de retiro.

El minorista Ducati autorizado solicitará una copia de su carta de notificación de propietario, y una copia de su factura pagada previamente. Inspeccionarán el vehículo, si aún lo tiene usted, antes de presentar un reclamo en su nombre a Ducati North America, Inc. para obtener un reembolso.

Solo la reparación de esta campaña de retiro por seguridad es reembolsable.



**CR310 – Check for Correct Positioning of ABS Fuses
and Corresponding Fuse Holders**
Panigale V2 MY 2025 (all versions)
Streetfighter V2 MY 2025 - 2026 (all versions)
Safety Recall Campaign SRV-RCL-25-004



030300000100
0000001

Your authorized Ducati retailer will request a copy of your owner notification letter, as well as, a copy of your previously paid invoice. They'll inspect the vehicle, if still in your possession, prior to submitting a claim on your behalf to Ducati North America, Inc. for reimbursement.

Only a repair involving this safety recall campaign is reimbursable.

We recommend that your authorized Ducati dealer be your primary contact on this issue. We anticipate that your authorized Ducati dealer will be able to answer any questions that you may have regarding your qualifications for reimbursement of a previous repair; additionally, our Client Relations Dept. may be contacted at 855-801-2716 for any special assistance required.

What if you no longer own the vehicle?

If you no longer own the vehicle, please e-mail your change of ownership information to Contact_Us@ducati.com or contact Ducati North America Client Care at 855-801-2716.

We regret any inconvenience to you from this action; however, your safety and satisfaction are important to us.

Sincerely,

Richard Kenton
Technical Director – Ducati North America



CR310 – Revise la posición correcta de los fusibles de ABS y portafusibles correspondientes

Panigale V2 modelo 2025 (todas las versiones)

Streetfighter V2 modelos 2025 - 2026 (todas las versiones)

Campaña de retiro por seguridad SRV-RCL-25-004

Recomendamos que el concesionario autorizado Ducati sea su contacto principal en este problema. Anticipamos que el concesionario Ducati autorizado podrá responder cualquier pregunta que tenga sobre los requisitos para el reembolso de una reparación anterior; además, puede llamar a nuestro Departamento de Relaciones con los Clientes al 855-801-2716 para recibir cualquier asistencia especial que necesite.

¿Qué sucede si ya no es propietario del vehículo?

Si ya no es propietario del vehículo, envíe un correo electrónico con la información del cambio de propietario a Contact_Us@ducati.com o comuníquese con Servicio al Cliente de Ducati North America llamando al 855-801-2716.

Lamentamos cualquier inconveniente que esta acción le pueda causar; sin embargo, su seguridad y satisfacción son importantes para nosotros.

Atentamente,

Richard Kenton
Director Técnico, Ducati North America