

IMPORTANT SAFETY RECALL NOTICE

NHTSA Recall No. 25V-907

This notice applies to your motorcycle, VIN: «Vin»
«PdiFirstName» «PdiLastName»
«PdiAddress1»
«PdiCity», «PdiProvince» «PdiPostalCode»

2/16/2026

RE: Affected models:

2025 390 SMC R, 2025 390 ENDURO R, 2025 390 ADVENTURE R, 2025 390 ADVENTURE X

Dear KTM Customer,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

KTM North America, Inc. has decided that a defect which relates to motor vehicle safety exists with certain model motorcycles listed above.

Engine vibrations may cause the side stand spring on forged side stands to break.

A broken side stand spring may cause the side stand to deploy while the motorcycle is in motion, potentially turning off the ignition and increasing the risk of a crash.

To remedy this defect, dealers will install a new side stand spring that has a rubber protector mounted and will also install a new side stand sensor retaining plate on all affected motorcycles, free of charge.

It is recommended that the side stand be secured for the journey to a dealer. This can be done, for example, with a heavy-duty rubber strap or something similar.

Please contact your authorized KTM dealer (log onto www.ktm.com for a complete dealer listing) as soon as possible to arrange having the new side stand spring with rubber protector and new side stand sensor retaining plate replaced. It is suggested that you call your local authorized KTM dealer to make an appointment to have the recall repair performed. The procedure will take approximately 30 minutes. However, it may be necessary to leave your motorcycle with the dealer for a longer period of time depending on their work schedule and if they need to order replacement parts. Please present a copy of this letter along with your motorcycle to your local authorized KTM dealer.

If you have any questions related to the content of this letter, please contact KTM North America Customer Relations at (888) 985-6090 for assistance.

If your dealer fails or is unable to remedy this defect without charge, or within a reasonable amount of time, you may submit a written complaint to Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590 or call 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.nhtsa.gov>

If you have sold, traded or no longer own this motorcycle, it is important for the safety of the current owner that you inform KTM North America of current ownership or unknown ownership status by returning the second page of this letter in the enclosed self-addressed prepaid postage envelope.

If you are a vehicle lessor, Federal Regulations require you to forward this notice to your lessee within ten days.

If you have already paid for a repair related to this concern before the date of this letter, you may be eligible for reimbursement. Please contact KTM motorcycles Customer Relations at the number above for more information.

We apologize for any inconvenience and want to assure you that our commitment together with all KTM Dealers is to provide you with the highest level of service, support and customer satisfaction.

Best Regards,

KTM NORTH AMERICA, INC.

30125 KTM Way // Murrieta, CA 92563
1119 Milan Avenue // Amherst, OH 44001
www.ktm.com

The KTM logo is displayed in a bold, black, italicized font against a solid orange background.

READY 
TO RACE

Dealer Services Department
KTM North America, Inc.

KTM NORTH AMERICA, INC.

30125 KTM Way // Murrieta, CA 92563
1119 Milan Avenue // Amherst, OH 44001
www.ktm.com

