

RECALL 25V113 REMEDY INSTRUCTIONS



Make(s): STARCRAFT
Model(s): STARCRAFT ALLSTAR
Model Year(s): 2024

Concern:
In certain vehicles, the egress handle(s)
may not be visible to an operator standing in
the aisleway.

Repair Code: RC-047-00-01-004338
Allotted Time: 1.50 HRS.
Inspection Code: N/A
Allotted Time: N/A
Photo(s) Required: NO
Prior Authorization Required: YES
Part(s) Kit Number: N/A
Part(s) Return: N/A

Place vehicle in (P) Park and engage the Parking Brake. Block any tires/wheels to prevent the vehicle from rolling. Failure to do so may result in electrocution, fire or other personal injury, property damage and/or death.

CERTAIN: 2024 STARCFRAT ALLSTAR TRANSIT BUSES

PARTS KIT ORDER:

QTY: 2 – Windows, Egress

QTY: 2 – Interior Trim Rings

(TOTAL OF 2EGRESS WINDOWS, 2 INTERIOR TRIM RINGS, WINDOW SEAL TAPE AND BATCH OF FASTENERS)

REMEDY:

STEP 1: LOCATE THE EXISTING EGRESS WINDOWS IN THE BUS;

- DISCARD ALL WINDOWS, FASTENERS AND INTERIOR TRIM RINGS;

STEP 2: REMOVE THE TWO WINDOWS;

STEP 3: PREP THE WINDOW OPENING BY CLEANING ANY DEBRIS LEFT OVER FROM REMOVING THE OLD WINDOW;

- INCLUDING SEALANT;

STEP 4: PREP THE REPLACEMENT EGRESS WINDOWS BY CLEANING THE FLANGES OF THE EGRESS WINDOW;

- INSTALL FOAM SEAL TAPE AROUND THE PARAMETER OF THE EGRESS WINDOW FLANGE;

STEP 5: INSTALL THE APPROPRIATE REPLACEMENT EGRESS WINDOW INTO THE OPENINGS;

- USE THE NEWLY PROVIDED INTERIOR TRIM RING;
- USE THE NEWLY PROVIDED FASTENERS;

STEP 6: CLEAN INTERIOR AND EXTERIOR AROUND WINDOW AND ANY DEBIS;

STEP 7: TEST FUNTIONALITY OF THE NEW EGRESS WINDOWS;

STEP 8: CLAIM REPAIR CODE.