



Service Bulletin

American Honda Motor Co., Inc.

CB300R #1
April 2025

SAFETY RECALL

CB300R/RA HEADLIGHT ASSEMBLY

BACKGROUND

Honda is launching a **SAFETY RECALL** on **CERTAIN 2019 - 2025 CB300R/RA motorcycles** to replace the headlight assembly. Due to a manufacturing defect, the headlight's internal circuitry may become damaged due to road and engine vibrations experienced during normal vehicle operation. The headlight may begin to flicker and eventually shut off, potentially increasing the risk of a crash or injury.

AFFECTED UNITS

As of March 31, 2025, you **MUST NOT SELL** any **AFFECTED NEW or USED 2019 - 2025 CB300R/RA** motorcycle until it is repaired according to this Service Bulletin. Additionally, you **MUST NOT SELL** or **INSTALL** any affected headlight with part number 33100-K94-T02.

- To search for applicable recalls on a specific unit, you **MUST** use *Unit Information* on **iN**.
- To manage your affected new inventory, use your dealer *eResponsibility Report* on **iN**.

CUSTOMER NOTIFICATION

American Honda intends to mail customer letters to all owners of affected 2019 - 2025 CB300R/RA motorcycles in May 2025. Customers will be informed that their motorcycle may be affected by a safety related defect and will be advised to make an appointment with an authorized Honda dealer for repair.

PARTS INFORMATION

Parts are currently unavailable and expected by the end of May 2025.

SERVICE BULLETIN

CB300R #1, which includes all the information relating to this Safety Recall, is expected to be issued in April 2025.

DEALER REPAIR RESPONSIBILITY

- Repairs must be performed by a qualified technician.
- Performing this repair exactly as shown in Repair Procedure instructions is critical for the remedy to be effective. Carefully follow all instructions.
- Service Management should inspect and confirm the repair.
- Dealer submission of a warranty claim affirms this repair was properly performed.

1 of 1