

Special Coverage

N252494003 L87 Engine Loss of Propulsion



Release Date: May 2026

Revision: 04

Revision Description: This bulletin is being revised to update the parts table to remove references and part numbers for Mobil 1 Supercar 0W-40 Oil. Please discard all previous copies of bulletin N252494003. *(*Updated Information).*

Attention: The following Mobil 1 FS 0W-40 information applies to U.S. and Canada dealers only. Other markets, including Mexico, and Export markets, will be communicated once available.

**This update is to inform US and Canada dealers that the transition from Mobil 1 Supercar 0W-40 to Mobil 1 FS 0W-40 is now complete for this recall. Claims for repairs performed using Mobil 1 Supercar 0W-40 prior to May 1, 2026 will be accepted and reimbursed. Effective May 1, 2026 and onward, only claims for repairs completed using Mobil 1 FS 0W 40 will be accepted and reimbursed.*

As a reminder, 0W-40 FS is available at a competitive price and should be used for all customer paid maintenance visits.

| Make | Model | Model Year | |
|-----------|----------------|------------|------|
| | | From | To |
| Cadillac | Escalade | 2021 | 2024 |
| Cadillac | Escalade ESV | 2021 | 2024 |
| Chevrolet | Silverado 1500 | 2021 | 2024 |
| Chevrolet | Suburban | 2021 | 2024 |
| Chevrolet | Tahoe | 2021 | 2024 |
| GMC | Sierra 1500 | 2021 | 2024 |
| GMC | Yukon | 2021 | 2024 |
| GMC | Yukon XL | 2021 | 2024 |

Attention: Involved vehicles are identified on the Applicable Warranties section in Investigate Vehicle History (IVH). This site should always be checked to confirm vehicle involvement prior to beginning any required inspections and/or repairs.

| | |
|-------------------------|--|
| Condition | Certain vehicles listed above, may have a condition where the connecting rod and/or crankshaft engine components in these vehicles may have manufacturing defects that can lead to engine damage and engine failure. |
| Special Coverage | <p>This special coverage covers if an engine failure occurs in the vehicle as a result of the condition described above for a period of 10 years or 150,000 miles (240,000 km), whichever occurs first, from the date the vehicle was originally placed in service, regardless of ownership.</p> <p>For vehicles covered by Vehicle Service Contracts, all eligible claims with repair orders on or after May 23, 2025, are covered by this special coverage and must be submitted using the labor operation codes provided with this bulletin. Claims with repair orders prior to May 23, 2025, must be submitted to the Service Contract provider.</p> <p>Vehicle owners or lessees who paid for repairs referenced in this Special Coverage ("Customers") are eligible for reimbursement of their reasonable and customary expenses in accordance with the procedures specified below. The conditional right to reimbursement is provided by GM solely in the interest of customer satisfaction and is personal to Customers. <i>Customers may not assign and GM does not consent to any assignment of any Customer's right to submit reimbursement claims, or to receive reimbursement, or any other rights granted by this Special Coverage to any third party, including but not limited to service contract providers, and this Special Coverage is not intended to and does not confer any third party beneficiary, subrogation or contribution rights, or any other rights to reimbursement, against GM, whether in law, equity or otherwise, on any third parties.</i></p> |
| Correction | Dealers are to replace the engine. The repairs will be made at no charge to the customer. |

Parts

| Quantity | Part Name | Part No. |
|----------|-----------------------------|----------|
| 1 | ENGINE* | 12740076 |
| 1 | ENGINE* | 19420611 |
| 1 | BELT, ACSRY DRV PRIM | 12669858 |
| 1 | BELT, ACSRY DRV AUX | 12658178 |
| 1 | SEAL, A/C CMPR & CNDSR HOSE | 13579648 |

Special Coverage

N252494003 L87 Engine Loss of Propulsion



| | | |
|----|---|--------------------------------|
| 1 | SEAL, A/C CMPR & CNDSR HOSE | 13579649 |
| 6 | BOLT,ENG MT FRM SI | 11549180 |
| 1 | GASKET, ENG OIL CLR | 23129010 |
| 2 | RETAINER,TRANS FLUID CLR PIPE CONN | 22988272 |
| 1 | SEAL,EXH SYS | 15035747 |
| 1 | SEAL,EXH SYS | 15077362 |
| 8 | GASKET,INT MANIF | 12626354 |
| 2 | GASKET,W/PMP | 12682391 |
| 2 | SEAL,TRANS FLUID CLR PIPE FTG | 85639955 |
| 8 | BOLT,ENG MT ENG SI | 11548998 |
| 10 | BOLT,EXH MANIF | 11546600 |
| 2 | GASKET,EXH MANIF | 12657093 |
| 1 | PIPE,FUEL FEED INTER | 12679463 |
| 1 | PIPE,FUEL FEED INTER | 12703668 |
| 2 | SEAL KIT,F/INJR O-RING* | 12726902 |
| 2 | SEAL KIT,F/INJR O-RING* | 19432442 |
| 1 | GASKET,F/PMP BRKT | 12679867 |
| 1 | SEAL,OIL LVL IND | 24504031 |
| 8 | OIL, ENG MOBIL 1 FS 0W40 (Quart) | 88862479 (US) |
| 8 | OIL, ENG MOBIL 1 FS 0W40 (55 Gallon Drum) | 88862480 (US) 19542035 (CA) |
| 8 | OIL,ENG 0W20 Dexos | 19432331(US) 19432456(CA) |
| 4 | COOLANT,ENG (1 GALLON) Dexcool | 12346290(US) 10953464(CA) |
| 1 | HOSE ENGINE OIL COOLER | 85724972 |
| 1 | RADIATOR* | 85575817 |
| 1 | RADIATOR* | 85575818 |
| 1 | RADIATOR* | 85575815 |
| 1 | RADIATOR* | 85575814 |
| 8 | Flywheel Bolts (2021 MY only) | 11569956 |

*Note: Use the VIN and the GM Electronic Parts Catalog (EPC) to determine which part to order if two or more part numbers are listed for the same part, as it may vary by vehicle options.

Reminder: Parts may be removed from SPRINT and Retail Inventory Management (RIM) and be non-returnable. Dealers should review the affected parts to confirm RIM managed status. Parts may have quantity limiters in effect. There are a small number of vehicles anticipated that will need this fix. **Due to the limited initial parts availability, dealers are encouraged not to order these parts for use as shelf stock.**

Note: Choose the applicable one of the oil parts numbers above, Oil/Fluid will be supplied by your Oil Distributor.

Warranty Information

| Labor Operation | Description | Labor Time | Trans. Type | Net Item |
|--|--|--|-------------|----------|
| For vehicles WITHIN the New Vehicle, Powertrain Limited Warranty or CPO Powertrain Warranty, utilize the regular warranty labor op. | Engine Replacement | | ZREG | N/A |
| | Escalade/Tahoe/Suburban/Yukon/Yukon XL | | | |
| | 2WD w/ F47 | 18.3 | | |
| | 2WD w/o F47 | 18.2 | | |
| | 4WD w/ F47 | 18.4 | | |
| | 4WD w/o F47 | 18.3 | | |
| | Silverado/Sierra | | | |
| | 2WD | 18.5 | | |
| | 4WD | 18.6 | | |
| | | ADD TIMES (applies to all vehicles/option combinations): | | |
| | Recover/Recharge R1234YF AC system | 1.2 | | |
| | Recover/Recharge R134A AC system | 0.3 | | |
| | Inspection and Diagnosis | 1.0 | | |

Special Coverage

N252494003 L87 Engine Loss of Propulsion



| | | | | |
|--|---|-----------|------|-----|
| For vehicles OUTSIDE of the New Vehicle, Powertrain Limited Warranty or CPO Powertrain Warranty, utilize labor op 9900927 | | | | |
| 9900928 | Diagnosis Only – No Further Action Required | Up To 1.0 | ZREG | N/A |
| 9900929 | Customer Reimbursement Approved - For USA and Canada dealers only - For Export dealers only | N/A 0.2 | ZREG | ** |
| 9900930 | Customer Reimbursement Denied – For USA dealers only | N/A | ZREG | *** |

** For USA and Canada: Submit the dollar amount reimbursed to the Customer in Net/Reimbursement. Submit \$20.00 USD (\$25.00 CAD) administrative allowance in Net/Admin Allowance.

For Export: Submit the dollar amount reimbursed to the Customer in Net/Reimbursement.

*** Submit \$10.00 administrative allowance in Net/Admin Allowance.

Please Note: The above labor time(s) are published direct from the Labor Time Guide.

Service Procedure

1. Verify any of the field actions (N252494000, N252494001, N252494002) have been completed and closed in IVH prior to moving forward with this bulletin.
2. A vehicle may come in with a seized engine, P0016 code, or a knocking noise.
3. If a vehicle is exhibiting any of these conditions, check it for basic maintenance/neglect.
 - If the vehicle is not showing any obvious signs of neglect and has a seized engine or a P0016 code, replace the engine. Refer to *Engine Replacement* in SI.
 - If the vehicle IS showing signs of neglect such as low/no oil level, has been hydrolocked, etc, the vehicle is **NOT** covered under this special coverage.
 - If the vehicle has a knocking noise, run the L87 PicoScope Test per field action #N252494000. Determine whether to replace the engine based on the results of that test.
 - If the vehicle has a valvetrain or other top end issue, it is **NOT COVERED** under this special coverage.

Courtesy Transportation – For USA & Canada

Courtesy transportation is available for Customers whose vehicles are involved in a product program and still within the warranty coverage period. See General Motors Service Policies and Procedures Manual for courtesy transportation program details.

Customer Notification

General Motors will notify Customers of this special coverage on their vehicle.

Customer Reimbursement

Customer requests for reimbursement of previously paid repairs to correct the condition described in this bulletin are to be submitted to the dealer prior to or by May 31, 2026. See General Motors Service Policies and Procedures Manual (USA & Canada) or local Policies and Procedures, for details.

Special Coverage
N252494003 L87 Engine Loss of Propulsion



GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the tools, equipment, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your dealer for information on whether your vehicle may benefit from the information.



**We Support
Voluntary Technician
Certification**