

**SAFETY RECALL**  
NORTH AMERICA  
**Airbag Light On**



Reference: 08C / NHTSA 25V-298

FCA US LLC



**RAM**

Remedy available for  
2019-2024 (DT) RAM 1500 Pickups

Template Version 1.0

Revision	Edition	Detail
0	May 2025	Initial Version.

**SYMPTOM DESCRIPTION**

The Drivers Air Bag (DAB) squib connector(s) on about 75 of the above vehicles may be improperly secured. One or more improperly secured DAB squib connectors may prevent the DAB from deploying, or deploying properly, which can increase the risk of occupant injury in certain types of crashes.

The condition described above does not comply with Federal Motor Vehicle Safety Standard (FMVSS) No. 571.208 S4.1.5.3, requires that "[e]ach passenger car manufactured on or after September 1, 1997 shall comply with the requirement of S4.1.5.1(a)(1) by means of an [air bag] at the driver's and right front passenger's position." One or more improperly secured DAB squib connectors may prevent the DAB from deploying, or deploying properly, in certain types of crashes.

**SCOPE**

This recall applies only to the above vehicles.

NOTE: Some vehicles above may have been identified as not involved in this recall and therefore have been excluded from this recall.

**REPAIR TO BE PERFORMED**

All vehicles in this recall have been remedied. There is no action required.

**OWNER NOTIFICATION / SERVICE SCHEDULING**

All involved vehicle owners known to FCA are being notified by first class mail.

**ADDITIONAL INFORMATION**

If you have any questions or need assistance in completing this action, please contact your Service and Parts District Manager.

Customer Services / Field Operations  
FCA US LLC.