

RRC-82-25-002-1: Inoperative Front Turn Signals

Rivian has decided that certain model year 2025 Rivian R1S and R1T do not conform to Federal Motor Vehicle Safety Standard (FMVSS) 108 and Technical Standards Document (TSD) 108. These vehicles may have been built with lower front fascia lamps that have inoperative turn signals. Turn signals on the exterior mirrors and on the rear of the vehicle are not affected. Rivian is not aware of any crashes, injuries, or fatalities related to this condition. Pursuant to its recall determination, Rivian will replace the affected lamps on the affected vehicles.

Document Type	Safety Recall Bulletin
Date	September 22, 2025
Affected Region(s)	USA, Canada
Affected Model(s)	R1T, R1S
Model Year(s)	2025
Approximate Build Dates	May 2024-May 2025
 Refer to Open Containments in ServiceOS to determine if this document applies to a specific vehicle.	
Vehicle System	82 - Lighting
Minimum Service Location	Mobile

Potentially Required Parts

Part Number	Quantity	Engineering Name	Service Name/Notes
PT00882632-E	1	DIRECTION INDICATOR LAMP LH	Lamp, Fascia, Lower, LH
PT00882633-E	1	DIRECTION INDICATOR LAMP RH	Lamp, Fascia, Lower, RH

! **Attention:** The parts listed in this table are only for unique steps that are called out in this bulletin. Some sections of this bulletin might refer to Service Manual procedures which require additional parts. Always review the bulletin and all potentially related Service Manual procedures before ordering parts and beginning work.

! **Important:** Refer to ServiceOS to determine which lower fascia lamps require replacement.

Procedure

On the affected side(s): Replace: Lamp, Fascia, Lower (refer to service manual procedure 821014010).

Labor Codes

Labor Code	Description
RRC822500200	RRC-82-25-002 not applicable
RRC822500201	Replace LH lower fascia lamp
RRC822500202	Replace RH lower fascia lamp
RRC822500203	Replace LH and RH lower fascia lamps
<i>Contact ServiceDocumentFeedback@rivian.com regarding labor codes and document content.</i>	