 Tesla, Inc. Service Bulletin		<h2>Replace Steering Wheel to Address Improper Horn Ground Wire Connection</h2>	
SB-25-17-009 August 6, 2025			
Classification		Section/Group	Mobile Service
Recall Bulletin		17 - Electrical	Cannot Perform
Model	Model Year	Country/Region	Build Location
Model Y	2026	United States	Fremont, Giga Texas
<small>The model(s) and model year(s) listed are a general approximation of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.</small>			


Recall Bulletin: Recall Bulletins are mandatory service procedures that, unless they can be completed via a software update that a customer installs through the normal course of ownership, must be carried out by Tesla-certified Service Centers. Recall work performed by uncertified technicians could lead to unsafe conditions or voided warranty provisions.

Condition

On certain Model Y vehicles, the horn ground wire may not have been properly connected, which may cause the horn to be inoperable.

Correction

Replace the steering wheel assembly.

 **NOTE:** If this bulletin is applicable to the vehicle, perform the correction without any need for inspection.

Correction Description	Correction	Time
Replace Steering Wheel to Address Improper Horn Ground Wire Connection	S012517009	0.18

Part Number	Description	Quantity
Parts Required 2003660-00-E or 2003660-00-F	STEERING WHEEL ASSEMBLY	1
<small>These part numbers were current at the time of publication. Use the revisions listed or later, unless otherwise specified in the Parts Catalog.</small>		

Procedure

Replace the steering wheel assembly (refer to Service Manual procedure [3205010802](#)).