

SERVICE PROCEDURE

25514
October, 2025

SUBJECT: INTERIM NOTICE SAFETY RECALL
Under Floor Reinforcement in certain 2016 thru
2026 IC Bus™ CE series school buses built
01/15/2015 thru 05/29/2025 and 2016 thru 2022
IC Bus RE series school buses built 03/09/2015
thru 03/23/2021

CUSTOMER LETTER

Print ready (PDF file) copy of the [Customer Letter](#)

DEFECT DESCRIPTION

The suspect vehicles do not conform to Federal Motor Vehicle Safety Standards (FMVSS):

- No. 210, S4.2.2: The anchorages, attachment hardware, and attachment bolts for any of the following seat belt assemblies shall withstand a 13,345 N (3,000 pound) force applied to the lap belt portion of the seat belt assembly simultaneously with a 13,345 N (3,000 pound) force applied to the shoulder belt portion of the seat belt assembly, when tested in accordance with, at the choice of the manufacturer, S5.2.

And:

- No. 222, S5.1.4 Seat performance rearward. When a school bus passenger seat that has another seat behind it is subjected to the application of force as specified in S5.1.4.1 and S5.1.4.2.

Noncompliance to FMVSS 210 S4.2.2 and 222 S5.1.4 may increase the passenger's risk of personal injury or death in the event of a crash.

MODELS INVOLVED

This safety recall involves certain 2016 thru 2026 IC Bus™ CE series school buses built 01/15/2015 thru 05/29/2025 and 2016 thru 2022 IC Bus RE series school buses built 03/09/2015 thru 03/23/2021 with a side emergency door (feature codes 00047DCJ, 00047DCL, 47DCP, or 47DCT), luggage compartments, and dual riser seats.

ELIGIBILITY

Vehicle will be marked in the International® Service PortalSM with Safety Recall 25514 when the final remedy is released.

ACTIONS YOU SHOULD TAKE

A final remedy has been determined. Parts are on order, but availability is currently unknown. A second notice will be sent to you once the final remedy is available.

IC Bus, LLC