

 Tesla, Inc. Service Bulletin		<h2>Update Vehicle Software to Command Compliant Front Parking Lamp Brightness</h2>	
SB-25-00-008 October 23, 2025			
Classification		Section/Group	Mobile Service
Recall Bulletin		00 - Inspection & Service	Can Perform (where permitted)
Model Year	Model	Country/Region	Build Location
2024 - 2026	Cybertruck	North America	Giga Austin
<small>The model(s) and model year(s) listed are a general approximation of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.</small>			

Recall Bulletin: Recall Bulletins are mandatory service procedures that, unless they can be completed via a software update that a customer installs through the normal course of ownership, must be carried out by Tesla-certified Service Centers. Recall work performed by uncertified technicians could lead to unsafe conditions or voided warranty provisions.

Condition

Certain Cybertruck vehicles manufactured between November 13, 2023, and October 11, 2025, and operating with software versions prior to 2025.38.3, may require a vehicle software update to ensure that the front parking lamp brightness complies with regulatory standards.

Correction

Inspect the vehicle software version, and if necessary, update the vehicle software to version 2025.38.3 or later.

Correction Description	Correction	Time
Inspect Vehicle Software Version; No Update Necessary	S012500008	0.06
Inspect And Update Vehicle Software to Command Compliant Front Parking Lamp Brightness	S022500008	0.06

NOTE: This document is a Vehicle Software Update bulletin that has unique functionality. There is no need to add the bulletin correction code to the Service Visit. This bulletin will appear in the vehicle’s “Outstanding Work” and will be automatically removed from “Outstanding Work” after the remedy software update is installed.

Procedure

On the vehicle touchscreen, touch **Controls** (vehicle icon) > **Software**, and then scroll down to display the vehicle software version.

- If the vehicle is operating with software version 2025.38.3 or later, no further action is necessary. Use correction code S012500008.
- If the vehicle is operating with a software version earlier than 2025.38.3, update to version 2025.38.3 or later (refer to Service Manual procedure [00020003](#)). Use correction code S022500008.