



Thor Motor Coach Recall Repair Instructions

Recall #	25V-791 2025-634		
Description/Title:	Solar Panel		
Affected Product Line(s):	Certain MY 2022-24 Sequence and Tellaro, 2023 Sanctuary and Tranquility, 2023-24 Twist and Dazzle, 2024 Freedom Elite Van		
Service Campaign # :	RC000336		
Repair Code:	Inspect Only: TMCRC80505Y Inspect with Repair: TMCRC80505V	Document Date:	1/8/2026
Time Allowed:	Inspect Only: 0.2 Inspect with Repair: 0.5	Document Revision:	A

Issue:

It has been discovered that the hardware used to mount the solar panels to the roof brackets may be missing the washer on the bolts at each of the four brackets.

Inspection:

1. Inspect to determine solar panel type. If the coach has a flexible adhesive mounted solar panel, stop, this recall does not apply.
2. If the coach has a hard aluminum frame, inspect the solar panel bracket hardware for the existence of the washers. If both washers are present on each bracket, stop, no further action is required. If washers are missing, proceed to repair instructions.

Instructions:

1. Two ¼" stainless steel washers from local shop supplies are to be installed at each of the four brackets as shown in diagram:

