

## 25V-799 WAY-105 Incorrect Cargo Carrying Capacity Label

**Purpose:** Replace incorrect OCCC label with a correct OCCC label.

**Models:** 2026 Open Trail Motorhomes

**FLAT RATE CODE & TIME ALLOWED** *To file the warranty claim for payment, please use the following flat rate code. Involved and label corrected - 8809RC01 for 0.25 hours.*

**No authorization is required for work completed at the flat rate times stated on the work instructions.**

Use **“WAY-105”** as the authorization on claim for payment.

Tools Needed:

Alcohol wipe or equivalent surface cleaner

Parts Needed:

OCCC label included with owner letter

### Work instructions:




Figure 1

1. The yellow Cargo Carrying Capacity Label can be found on the driver's side door frame, Figure 1.
2. Wipe off the old label with isopropyl alcohol.
3. Carefully place the new label directly on top of the old label.