



February, 2026

***** IMPORTANT SAFETY RECALL REMINDER *****

According to our records, your 2018 Navigator has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number and Description: 25S31 - Front Seatbelt Retractor Date Code Inspection

What is the issue? On some of the affected vehicles, the driver and/or front passenger seatbelt retractor pretensioners may deploy inadvertently while the vehicle's engine is on.

If you already had 24S06 performed on your vehicle, Ford is looking to inspect your vehicle again for more pretensioner date codes that have been determined to be defective.

Inadvertent deployment of the retractor pretensioner will result in the seatbelt being locked in position and will not retract or extend, which is noticeable to the occupant. A seatbelt that does not retract or extend may result in injury in the event of a crash.

If you have questions or concerns, please contact our **Lincoln Recall Assistance Center (RAC) at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: lincoln.com/support.

Thank you for your attention to this very important matter.

Febrero de, 2026

***** RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD *****

SegUR nuestros registros, no se realizaron en sur 2018 Navigator las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: 25S31 - Inspección del código de fecha del retractor del cinturón de seguridad delantero

¿Cuál es el problema? En algunos de los vehículos afectados, los pretensores del retractor del cinturón de seguridad del conductor y/o del pasajero delantero pueden desplegarse inadvertidamente mientras el motor del vehículo está encendido.

Si ya realizó la 24S06 en su vehículo, Ford desea inspeccionar su vehículo nuevamente para detectar más códigos de fechas de pretensores que se haya determinado como defectuosos.

El despliegue inadvertido del pretensor del retractor provocará que el cinturón de seguridad quede bloqueado en su posición y no se retraiga ni se extienda, lo cual es perceptible para el ocupante. Un cinturón de seguridad que no se retrae ni se extiende puede provocar lesiones en caso de choque.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de asistencia de campañas (RAC) Lincoln al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: lincoln.com/support.

Gracias por su atención en este asunto sumamente importante.



L I N C O L N

P.O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C

1136432 A / 000000000000992 / 27



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION

REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION

