



February, 2026

***** IMPORTANT SAFETY RECALL REMINDER *****

According to our records, your 2025 Mustang Mach-E has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number and Description: **25C25 - Park Rod Replacement**

What is the issue? On your vehicle, the transmission's park rod assembly may not properly engage the park pawl, preventing the vehicle from locking into Park when Park (P) is selected. If this condition occurs, a wrench light and shift system fault message will be displayed in the instrument panel cluster. Additionally, the vehicle's Electronic Parking Brake (EPB) will automatically apply.

If the park pawl is not properly engaged and the Electronic Parking Brake (EPB) is not applied, your vehicle may experience a roll-in-park, increasing the risk of a crash.

If you have questions or concerns, please contact our **Ford Recall Assistance Center (RAC) at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: ford.com/support.

Thank you for your attention to this very important matter.

Febrero de, 2026

***** RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD *****

SegUR nuestros registros, no se realizaron en sur 2025 Mustang Mach-E las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: **25C25 - Reemplazo de la barra de estacionamiento**

¿Cuál es el problema? En su vehículo, es posible que el ensamble de la varilla de estacionamiento de la transmisión no acople correctamente el trinquete de estacionamiento, lo que impide que el vehículo se bloquee en P cuando se selecciona Estacionamiento (P). Si se produce esta condición, se mostrará una luz de llave inglesa y un mensaje de falla del sistema de cambios en el grupo de instrumentos. Además, se aplicará automáticamente el freno de estacionamiento electrónico (EPB) del vehículo.

Si el trinquete de estacionamiento no se acopla correctamente y el freno de estacionamiento electrónico (EPB) no está aplicado, su vehículo podría desplazarse mientras está estacionado, lo que aumenta el riesgo de choque.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de asistencia de campañas (RAC) Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: ford.com/support.

Gracias por su atenciic en este asunto sumamente importante.



P.O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C

1244850 A / 000000000000874 / 1



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION

REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION

